

JLRTB02127NAS7
TECHNICAL BULLETIN
13 MAY 2026



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This bulletin supersedes TSB JLRTB02127NAS6/2025 dated 05 NOV 2025, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in blue

SECTION:

303-03A

SUBJECT/CONCERN:

RESCINDED - Engine Coolant Level Low with no Visible Loss of Coolant - RESCINDED

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
Range Rover (LK)	2022-2024	000001-234058	Solihull
Range Rover Sport (L1)	2023-2024	000001-400762	Solihull

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

This bulletin has been rescinded with immediate effect. Use the TOPIx Workshop Manual to diagnose the vehicle concern.

CAUSE:

N/A

ACTION:

N/A