

Reference	SSM76457
Models	Defender / L663 New Range Rover / L460 New Range Rover Sport / L461
Title	Amber MIL Illuminated With DTC P2797-09 Stored In The TCM
Category	Driveability
Last modified	26-May-2026 08:19:00
Symptom	698298 Malfunction Indicator Lamp
Content	<p><u>Model /Model Year / Derivative</u> Range Rover (L460) / 24MY - 25MY / AJ20 P6 PHEV / 4.4L NC11 / 3.0L AJ20 P6H Range Rover Sport (L461) / 24MY - 25MY / 3.0L AJ20 D6H / AJ20 P6 PHEV / 4.4L NC11 / 3.0L AJ20 P6H Defender (L663) / 25MY onwards / Vehicles Equipped With Gen4 Transmission</p> <p><u>Situation:</u> JLR Engineering investigations have found customer reports of an Amber MIL being displayed on the Instrument Panel Cluster on vehicles equipped with a Gen4 transmission. The following Diagnostic Trouble Code (DTC) may be stored in the Transmission Control Module (TCM):</p> <ul style="list-style-type: none"> • P2797-09 <p><u>Action:</u> Refer to the service request below.</p> <p><u>Service Request:</u> Raise a Technical Assist (TA) to PTS_650 - ZF Transmission Engineering with the following information:</p> <ul style="list-style-type: none"> • Complete the Powertrain Data Collect and Transmission Data Collect referencing P2797-09. • Engineering will review the data and advise the appropriate repair action. <p>(Ref: 000410543 / 9147)</p>

anBhdhRlcnM7MjAyNi0wNS0yNiQxMjcyODo0C41NjVhOzEwOC4yOS43NS4xMDQ7