

<b>REFERENCE:</b>	<b>TSB:</b> 08-227-26 <b>GROUP:</b> 08 - Electrical	<b>Date:</b>	May 30, 2026	<b>REVISION:</b>	—
<b>VEHICLES AFFECTED:</b>	<b>2026 (MW) Jeep Compass</b> <b>2022 - 2026 (JJ) Jeep Avenger</b> This bulletin applies to vehicles equipped with 1.2L EB Turbo 3 Cyl MHEV Engine (Sales Code EJB).			<b>MARKET APPLICABILITY:</b> <input type="checkbox"/> NA <input type="checkbox"/> MEA <input type="checkbox"/> SA <input type="checkbox"/> IAP <input checked="" type="checkbox"/> EE <input type="checkbox"/> CH <b>NOTE:</b> This bulletin applies to the Enlarged Europe market.	
<b>CUSTOMER SYMPTOM:</b>	<b>Technicians may experience the following:</b> <ul style="list-style-type: none"> <li>• Fault code P0606-48 in the direct voltage transformer ECU.</li> </ul>				
<b>CAUSE:</b>	<b>Direct voltage transformer ECU DC/DC software</b>				

**DISCUSSION:**

This Information Only bulletin contains information helpful or useful for technicians in diagnosing. The presence of fault code P0606-48 in the direct voltage transformer ECU DC/DC does not cause any malfunction or lighting of a warning lamp on the instrument panel.

**No repairs are to be made.** Check that the fault code only appears in the direct voltage transformer ECU DC/DC. Do not confuse with P0606-49 in the front electric drive machine ECU (MCU (CMM\_E)).

Do not replace parts if there is only this fault code in the direct voltage ECU DC/DC.

**POLICY:**

Information Only.