

# 43-087: Engine Model Year 2021-2025 GHG Label Replacement

4/27/2026

 [Edit](#)  [Clone](#)

43-087

## Subject

Engine Model Year (EMY) 2021-2025 Greenhouse Gas (GHG) Label Replacement

## Whats New Abstract

Certain T680 / T800 / T880 / W900 / W990 have updated GHG labels available for order and installation.

## Revision

**04/27/2026:** Inspection steps have been added to the repair procedures, along with a new recommended repair for inspection only.

## Condition

An updated GHG label is available for order and installation. To ensure compliance with emissions regulations and avoid potential regulatory fines, this update will ensure that the chassis is equipped with the most accurate information.

## Chassis Affected

1,627 Canada vehicle model year 2022-2026 T680 / T800 / T880 / W900 / W990 manufactured between 01/12/2021 and 11/13/2025 equipped with an outdated GHG label

## Action

### Emissions Campaign

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. In Service Management, select campaign **43-087** to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the campaign in Service Management.
3. If you are not using Service Management to start repair orders, review SIR for Complete next to the **43-087** campaign code prior to performing this repair.
4. Follow the procedures in the Attachments section to replace the GHG label.

## Warranty

Starting on **04/03/2026** and for repairs completed by **05/01/2027**, Kenworth will pay for parts at dealer net plus applicable mark-up and labor:

- **0.3 hours** of labor to replace the current GHG label with an updated GHG label (includes photos

and TCS365 case). Select Recommended Repair Code **43-087A**.

- The claim must include a clear picture of both the original GHG label and the new compliant label as it is installed.
- **0.2 hours** of labor to inspect the GHG label only (no replacement required, includes photos). Select Recommended Repair Code **43-087B**.
  - The claim must include a clear picture of the compliant GHG label as it is installed.
- File an additional claim for extraordinary circumstances. A Recommended Repair for standard labor must be filed first.
- File the claim within 14 days in accordance with the Warranty Policy.

**Take-Off Parts Disposition:**

- Destroy 30 days after claim is paid

PRWS CLAIM CODING			
<b>Campaign Code</b>	43-087	<b>Campaign Type</b>	Field Repair
<b>Claim Category</b>	Truck	<b>Repair Type</b>	Proactive
<b>Customer Concern Code</b>	172 – Wrong Part	<b>Causal Code</b>	44 – Worn
<b>Corrective Action Code</b>	03 – Replace with New	<b>Responsibility Code</b>	CAMP-Campaign
<b>Failure Location</b>	053-005-021 – Label – Miscellaneous	<b>Causal Part</b>	S53-6198
<b>Supplier Code</b>	N/A	<b>SRT Code</b>	<p><b>B26-17A</b>  <b>0.3 Hours</b>            Bulletin 43-087: Engine Model Year 2021-2025 GHG Label Replacement            Recommended Repair: 43-087A</p> <p><b>B26-17B</b>  <b>0.2 Hours</b>            Bulletin 43-087: Engine Model Year 2021-2025 GHG Label Replacement            Recommended Repair: 43-087B</p>

Parts


Quantity	Part Number	Description

1	S53-6198	Label - Green House Gas
---	----------	-------------------------

## TCS365 Case Creation Guide for GHG Labels

Submission of a TCS365 case to **SPECIAL ORDERS** is required to order the correct chassis specific GHG label.

1. Open TCS365 in Google Chrome or Microsoft Edge
2. Select **Order Support | Order Inquiry**
3. Select Case Type: **Place an Order**
4. Select Case Category: **Labels**
5. On the **Label Order** page, fill in the following fields as shown and fill in the other fields as appropriate:
  - Account Name: *Appropriate for your dealer*
  - Vehicle Year: *Chassis model year*
  - Subject: **Engine Model Year 2021-2025 GHG Label Replacement**
  - Dealer PO#: *Dealer purchase order number*
  - Shipping method: *Select from drop-down list*
  - Part Number: **S53-6198**
  - Vehicle OEM: *Select from drop-down list*
  - Vehicle Chassis Number: **Last 8 digits of VIN**

 <b>NOTE</b>
<p>For fleets ordering GHG labels for multiple VINs, add a note in the Description field with "Multiple Fleet VINs". Complete the Multiple GHG Label Order Sheet linked in the Attachments section below and attach it via the Upload File button.</p>

## Procedure

 <b>WARNING!</b>
<p><b>Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps before performing any work and follow all dealership safety procedures or</b></p>

**precautions. Failure to comply may result in death, personal injury, equipment damage, or property damage.**

Please see the Attachments section below for procedures replacing the GHG label.

## Attachments

---

[43-087 Engine Model Year 2021-2025 GHG Label Replacement Chassis List](#)

[43-087 Engine Model Year 2021-2025 GHG Label Replacement Repair Procedure](#)

[43-087 Engine Model Year 2021-2025 GHG Label Replacement Customer Letter - English](#)

[Multiple GHG Label Order Sheet](#)

# 43-087: Engine Model Year 2021-2025 GHG Label Replacement

4/27/2026

 [Edit](#)  [Clone](#)

43-087

## Subject

Engine Model Year (EMY) 2021-2025 Greenhouse Gas (GHG) Label Replacement

## Whats New Abstract

Certain Model 367 / 389 / 567 / 579 / 589 have updated GHG labels available for order and installation.

## Revision

**04/27/2026:** Inspection steps have been added to the repair procedures, along with a new recommended repair for inspection only.

## Condition

An updated GHG label is available for order and installation. To ensure compliance with emissions regulations and avoid potential regulatory fines, this update will ensure that the chassis is equipped with the most accurate information.

## Chassis Affected

2,810 Canada vehicle model year 2022-2026 Model 367 / 389 / 567 / 579 / 589 manufactured between 01/29/2021 and 11/13/2025 equipped with an outdated GHG label

## Action

### Emissions Campaign

Service all chassis affected that enter your dealership, even if the customer has no issue with the chassis.

1. Review the attached chassis list for your dealer code and schedule your customer(s) for service if their chassis is on the list.
2. In Service Management, select campaign **43-087** to add it to the case. If the unit is released back into service without performing the repair, make sure to also release the campaign in Service Management.
3. If you are not using Service Management to start repair orders, review SIR for Complete next to the **43-087** campaign code prior to performing this repair.
4. Follow the procedures in the Attachments section to replace the GHG label.

## Warranty

Starting on **04/03/2026** and for repairs completed by **05/01/2027**, Peterbilt will pay for parts at dealer net plus applicable mark-up and labor:

- **0.3 hours** of labor to replace the current GHG label with an updated GHG label (includes photos

and TCS365 case). Select Recommended Repair Code **43-087A**.

- The claim must include a clear picture of both the original GHG label and the new compliant label as it is installed.
- **0.2 hours** of labor to inspect the GHG label only (no replacement required, includes photos). Select Recommended Repair Code **43-087B**.
  - The claim must include a clear picture of the compliant GHG label as it is installed.
- File an additional claim for extraordinary circumstances. A Recommended Repair for standard labor must be filed first.
- File the claim within 14 days in accordance with the Warranty Policy.

**Take-Off Parts Disposition:**

- Destroy 30 days after claim is paid

PRWS CLAIM CODING			
<b>Campaign Code</b>	43-087	<b>Campaign Type</b>	Field Repair
<b>Claim Category</b>	Truck	<b>Repair Type</b>	Proactive
<b>Customer Concern Code</b>	172 – Wrong Part	<b>Causal Code</b>	44 – Worn
<b>Corrective Action Code</b>	03 – Replace with New	<b>Responsibility Code</b>	CAMP-Campaign
<b>Failure Location</b>	053-005-021 – Label – Miscellaneous	<b>Causal Part</b>	S53-6198
<b>Supplier Code</b>	N/A	<b>SRT Code</b>	<p><b>B26-17A</b>  <b>0.3 Hours</b>            Bulletin 43-087: Engine Model Year 2021-2025 GHG Label Replacement            Recommended Repair: 43-087A</p> <p><b>B26-17B</b>  <b>0.2 Hours</b>            Bulletin 43-087: Engine Model Year 2021-2025 GHG Label Replacement            Recommended Repair: 43-087B</p>

Parts


Quantity	Part Number	Description

1	S53-6198	Label - Green House Gas
---	----------	-------------------------

## TCS365 Case Creation Guide for GHG Labels

Submission of a TCS365 case to **SPECIAL ORDERS** is required to order the correct chassis specific GHG label.

1. Open TCS365 in Google Chrome or Microsoft Edge
2. Select **Order Support | Order Inquiry**
3. Select Case Type: **Place an Order**
4. Select Case Category: **Labels**
5. On the **Label Order** page, fill in the following fields as shown and fill in the other fields as appropriate:
  - Account Name: *Appropriate for your dealer*
  - Vehicle Year: *Chassis model year*
  - Subject: **Engine Model Year 2021-2025 GHG Label Replacement**
  - Dealer PO#: *Dealer purchase order number*
  - Shipping method: *Select from drop-down list*
  - Part Number: **S53-6198**
  - Vehicle OEM: *Select from drop-down list*
  - Vehicle Chassis Number: **Last 8 digits of VIN**

 <b>NOTE</b>
<p>For fleets ordering GHG labels for multiple VINs, add a note in the Description field with "Multiple Fleet VINs". Complete the Multiple GHG Label Order Sheet linked in the Attachments section below and attach it via the Upload File button.</p>

## Procedure

 <b>WARNING!</b>
<p><b>Repair or maintenance procedures may pose a safety risk in limited circumstances. You must read all procedure steps before performing any work and follow all dealership safety procedures or</b></p>

**precautions. Failure to comply may result in death, personal injury, equipment damage, or property damage.**

Please see the Attachments section below for procedures replacing the GHG label.

## Attachments

---

[43-087 Engine Model Year 2021-2025 GHG Label Replacement Chassis List](#)

[43-087 Engine Model Year 2021-2025 GHG Label Replacement Repair Procedure](#)

[43-087 Engine Model Year 2021-2025 GHG Label Replacement Customer Letter - English](#)

[Multiple GHG Label Order Sheet](#)