

 Connection offline

Reporting obligation

Transaction No.: **2076778/3**

93 Reporting obligation pre-repair: Q6/A6 e-tron high-voltage battery isolation igniter (pyrofuse) P1CAC00 in 008C

Release date: May 28, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A6 Sportback e-tron, S6 Sportback e-tron, Q6 e-tron, Q6 Sportback e-tron, SQ6 e-tron, and SQ6 Sportback e-tron	2025 2027	All	Not applicable

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header (Added MY)
2	08/19/2025	Revised title (Updated for clarity) Revised <i>Service</i> (Add information questions for charging)
1	02/05/2025	Initial publication

Customer statement:

- The vehicle can no longer be started.
- The red onboard supply warning lamp lights up in the instrument cluster.

Workshop findings:

- The complaint can be reproduced.
- The high-voltage battery isolation igniter was triggered.

The following DTC entry is logged as intermittent (passive) or static (active) in the control unit for hybrid battery management (diagnostic address 008C):

- **P1CAC00** (symptom ID: 42572): Hybrid/ high-voltage system pyrofuse triggered.
- Other event memory entries may also be logged in diagnostic address 008C.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

NOTICE

This reporting obligation does not apply in the following cases:

- Repair measures that are required due to an accident.
- Repair measures that have already been described in a TSB.

- Create a TAC Web ticket and identify it as “**Reporting obligation according to the Technical Service Handbook**”.
- Please do not carry out any repairs for now.
- Use the workshop code: *Energy, electrical system, data transfer* → *Power supply* → *High-Voltage Battery Switch Box*

If the complaint occurred while charging, ask the customer about the circumstances under which the complaint occurred and provide the information in the TAC case:

- Was the vehicle being charged using AC or DC?
- If known, please indicate the brand of the charging station or wallbox.
- If available, please provide the EVSE (Electrical Vehicle Supply Equipment) ID for the affected charging station (e.g. DE*IOY*E123401).

If you do not receive a reply from the TAC within two hours, perform the necessary repairs yourself.

Warranty

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

We reserve the right to only pay out for warranty claims after thorough checks if a reporting obligation is not observed. We apologize for any inconvenience caused if delays in processing occur as a result.

Additional Information

All part and service references provided in this TSB (**2076778**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.