

 Connection offline

Reporting obligation

Transaction No.: **2081156/2**

93 Reporting obligation pre-repair BEFORE opening HV battery: Q6/A6 e-tron: yellow or red HV onboard supply warning lamp

Release date: May 27, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A6 Sportback e-tron, S6 Sportback e-tron, Q6 e-tron, Q6 Sportback e-tron, SQ6 e-tron, and SQ6 Sportback e-tron	2025 2027	All	Not applicable

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Add Model Year)
1	03/20/2026	Initial publication

Customer states:

- The yellow or red high-voltage onboard supply warning lamp lights up in the instrument cluster.

Workshop findings:

- The complaint can be reproduced.
- At least one relevant event memory entry indicating an issue with the high-voltage battery is logged in diagnostic address 008C.
- Various event memory entries may be logged in diagnostic address 008C depending on the complaint.
- The high-voltage battery **must** be opened while working through Guided Fault Finding (GFF).

Technical Background

We are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.

Verify the condition.

If the vehicle is within the New Vehicle Limited Warranty, contact a TAC consultant before proceeding. Please attach the DTC and diagnostic log to the [TAC ticket/TAC Web Ticket](#).

If you do not receive a reply from TAC within two hours, perform the necessary repairs yourself.

We reserve the right to only pay out for warranty claims after thorough checks if a reporting obligation is not observed. We apologize for any inconvenience caused if delays in processing occur as a result.

Complaints already covered by a TSB in Elsa are exempt from this reporting obligation.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2081156**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.