

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
e-tron	2019 2020 – 2023	All	Battery Electric Vehicles With PR Codes: 0K3 0K9 G1X G1Z GP0
Q5 e quattro	2020 – 2025		
e-tron Sportback	2020 – 2023		
A8 e quattro	2020 – 2021		
A7 e quattro	2021 - 2022		
RS e-tron GT, Q4 e-tron, and Q4 Sportback e-tron	2022 – 2026		
e-tron GT	2022 – 2025		
Q8 e-tron, Q8 Sportback e-tron, SQ8 e-tron, and SQ8 Sportback e-tron	2024		
A6 Sportback e-tron, S6 Sportback e-tron, Q6 e-tron, SQ6 e-tron, Q6 Sportback e-tron, and SQ6 Sportback e-tron	2025 2027		
S e-tron GT	2026		

Customer states:

No customer concerns, it occurs while performing any other diagnostic/ repair work to the high voltage battery.

Workshop findings:

- No Relevant DTCs are stored.

Technical Background

This TSB is to make easier in future potential reviews to locate the leak testing of the HVB.

Production Solution

Not applicable.

Service

Additional Information

All part and service references provided in this TSB (2081990) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.