



Mitsubishi Motors North America, Inc.
TECHNICAL SERVICE BULLETIN

SUBJECT:

**Mi-PILOT ASSIST/ADAPTIVE CRUISE
STOPS WORKING**

No: TSB-26-54-002

Version: 1

Date: May 8, 2026

TO: Mitsubishi Motors US and Puerto Rico Dealer Principals, General Managers, Sales Managers, Service Managers, Service Advisors, Parts Managers, Technicians and Warranty Administrators

AFFECTED VEHICLES

2022 - 2025 Outlander vehicles equipped with MI-PILOT ASSIST W/ NAVI-LINK ADAPTIVE CRUISE

COMPLAINT

The customer may state that while driving on an unobstructed road, and on a clear day without any rain, snow, or direct sunlight, the Cruise Control/Mi-Pilot becomes disabled, and the "Driving Aids - Temporarily limited - Radar Interference" message is also displayed in the combination meter.

CAUSE

Do Not Replace Parts, MMNA is investigating this concern with DTC-C2582-97 for "Distance Sensor" stored in LASER/RADAR control unit. The system will reset upon key off and on cycle. We will share more information when it becomes available.

REMEDY

Ensure you login to the (Vehicle Data Collection System) VDCS system, perform an All-DTC check, and clear all the Diagnostic Trouble Codes (DTC).

Please contact Customer Connections via email to report vehicles with fault code C2582-97. Provide customer name, last 8-digits of VIN, and TSB-26-54-002 in the subject line and send an email to:

- **North and Southern states KY, TN, MS, AL, GA, FL, WV, VA, NC, SC: Grafton Patten, Connections Specialist: grafton.patten@na.mitsubishi-motors.com**
- **West and Southern states AZ, NM, KS, OK, TX, MO, AR, LA: Jessica Clink, Connections Specialist: jessica.clink@na.mitsubishi-motors.com**

WARRANTY

Submit a warranty claim with the defined language on a warranty claim using the labor operation code provided below.

<i>Labor Operation Code</i>	<i>54835700</i>
<i>Labor Time</i>	<i>0.3 Hrs</i>
<i>Complaint</i>	<i>Mi-PILOT ASSIST/ADAPTIVE CRUISE STOPS WORKING</i>
<i>Cause</i>	<i>Incorrect configuration of software</i>
<i>Remedy</i>	<i>MMNA is investigating the concern</i>

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and perform diagnosis and repairs on Mitsubishi vehicles, using Mitsubishi Motors approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate that a defect is present in any vehicle referenced in this document nor does it imply that the described repairs are covered under warranty. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.