



Service Bulletin

Bulletin No.: PIP6120B

Date: July, 2026

PRELIMINARY INFORMATION

Subject: Possible Stall Stumble Extended Crank Or Run Rough When Coming Out Of Auto Stop or On a Manual Start Event

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2026		All	All	1.3 L3T	CVT and 9T45
Chevrolet	Trailblazer	2026		All	All	1.3 L3T	CVT and 9T45

Involved Region or Country	North America
Condition	Potential engine stall or stumbling when coming out of auto stop event. On a manual start engine may also start and stall, start and run rough a few seconds then run normal or may have an extended crank time to start and run normal.
Cause	GM Engineering currently investigating this issue.

Correction

No repairs should be attempted at this time, as GM Engineering is actively investigating the issue and the PI will be updated or replaced with TSB once a determination has been made.

As a temporary workaround, if the concern only happens on an auto start, please advise the customer to deactivate the Auto Stop feature during each ignition cycle to help avoid this condition.

Version	3
Modified	06/03/2026 - Created on 06/18/2026- Updated to add transmission 9T45 07/17/2026 - Updated condition to include a manual start

