

Technical Service Bulletin (TSB)

Rear Driveshaft Out Of Balance

REFERENCE:	TSB: 03-003-26 GROUP: 03 - Differential and Driveline	Date:	July 16, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (JL) Jeep Wrangler This bulletin applies to vehicles built on or after March 02, 2026 (MDH 0302XX) and on or before March 09, 2026 MDH 0309XX).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to North America markets.	
CUSTOMER SYMPTOM:	Customers may comment on one or more of the following: - Vehicle exhibits a vibration that increases with speed that can be felt in the seat or floor. - Oil is leaking from the Constant Velocity (CV) joint cover.				
CAUSE:	Out of balanced rear driveshaft				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-131, date of issue July 16, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves replacing the rear drive shaft.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
16-30-01-9H	Shaft, Drive, Rear 1-Piece - Replace (1 - Semi - Skilled)	3 - Driveline	0.5 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

NOTE: Order by VIN to ensure the correct rear drive shaft is received.

Qty	Part No.	Description	Notes
1 (AR)	68567442AA	Shaft, Drive, Rear 1-Piece	
1 (AR)	68567443AA	Shaft, Drive, Rear 1-Piece	
1 (AR)	68567444AA	Shaft, Drive, Rear 1-Piece	
1 (AR)	68725329AA	Bolt Kit	

DIAGNOSIS:

If a customers VIN is listed in VIP or your RSU VIN list, perform the repair. **This RSU only applies to vehicles on the RSU VIN list.**

REPAIR PROCEDURE:

1. Is the vehicle on the RSU VIN list?
 - YES>>> Proceed to [Step 2](#).
 - NO>>> This bulletin does not apply.
2. Replace the rear drive shaft. Raise and support the vehicle. Refer to the detailed service procedures available in DealerCONNECT/ Service Library under: Service Info>03 - Differential and Driveline / Shafts, Axle/Drive/Half / Removal and Installation.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.