

 [26-01-057H - Fuel Filler Door Inspect & Replace \(LA31\)_\(posted 07.17.26\).pdf](#)

Hyundai Motor America (HMA) has launched Limited Coverage Campaign LA31: Fuel Filler Door Difficult To Open – Push Opener Inspection & Replacement.

A. Affected Vehicles:

1. VIN Identification: Use the 'Vehicle Information' screen in WebDCS to verify "Warranty Start Date" and ensure the vehicle is within New Vehicle Limited Warranty (NVLW), observing mileage prior to any repair work.

- a. Certain 2026MY Sonata (DN8) produced 03/03/2026 – 04/03/2026
 - i. Built by Hyundai Motor Company ("HMC")
- b. Certain 2026MY Sonata Hybrid (DN8 HEV) produced 02/09/2026 – 04/03/2026
 - i. Built by HMC

B. Campaign Description:

Certain 2026MY Sonata (DN8) and 2026MY Sonata Hybrid (DN8 HEV) vehicles may exhibit a fuel filler door that is difficult to open due to the push-type opener mechanism. **Technical Bulletin (TSB) 26-01-057H** provides instructions to inspect the fuel filler door push opener and, if necessary, replace the component to restore proper operation.

C. Campaign Document(s):

1. TSB 26-01-057H

- a. Available on [Hyundaidealer.com](#) > Service > Service Programs > HMA Tech Info > Campaign

D. Parts Ordering/Information:

1. Please refer to **Technical Service Bulletin (TSB) 26-01-057H** for parts ordering information.
2. A valid campaign VIN is required for parts ordering.

E. Action Required:

1. Confirm VIN eligibility for campaign via WebDCS.
2. Follow **TSB 26-01-057H** for service procedure to inspect the fuel filler door push opener and if necessary, replace the component to restore proper operation
3. **Submit campaign claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.

HMA Warranty Campaigns