

WORK DESCRIPTION FOR FIELD MEASURE

Code: 22P5496323

Version: 2.0

Update engine electronics (ME) control unit software

Model 167, 205, 213, 222, 238, 253

-  • Always use the **latest** XENTRY Diagnosis software release with all available add-ons.
- Make sure to follow the operation steps exactly as described in XENTRY Diagnosis!
- Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (greater than 12.5 V).
- If XENTRY Diagnosis is already connected to the vehicle, start with **operation step 2**.

-  If two or more software updates or SCN coding's are performed during one workshop visit or SCN coding operations are performed, operation items 02-4762 and 02-5058 must **only be invoiced once for each workshop order!**

Work Procedure:

1. Connect XENTRY Diagnosis.
2. Update engine electronics (ME) control unit software.
 -  To do so, select menu item "Quick test view → **N3/10 - Engine electronics 'MED40' for combustion engine 'M274' (ME)** → Adaptations → Control unit update → Update of control unit software".
 -  Then follow the user guidance in XENTRY Diagnosis.
3. Disconnect XENTRY Diagnosis.

Warranty Information:

Operation no.	Operation text	Target time	Accounting no./ damage code
02-9334	Update control unit software N3/10 - Engine electronics (ME) (with XENTRY Diagnosis connected)	0.1	54 963 23
02-4762**	Connect/disconnect diagnostic system (XENTRY Diagnosis)	0.1	54 963 23
02-5058**	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1	54 963 23

* The prescribed times are available in the relevant systems (e.g. XENTRY Operation Time).

**Operation item is to be invoiced only once for each workshop order!