

REFERENCE:	TSB: 08-291-26 GROUP: 08 - Electrical	Date:	July 22, 2026	REVISION:	—
VEHICLES AFFECTED:	2022 - 2024 (DT) RAM 1500 Pickup 2022 - 2024 (DJ) RAM 2500 Pickup This bulletin applies to vehicles equipped with Uconnect 5 Nav w 12.0" Display (Sales Codes UBQ and UEQ)			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: - Intermittently the HVAC page on the Display Screen Module will change temperature and blower speed and then freeze. - When on the HVAC page, the Display Screen Module may not respond to touch. All other pages operate as intended.				
CAUSE:	Under investigation				

DISCUSSION:

This Information Only bulletin provides guidance for a customer reported condition listed in the Customer Symptoms above.

Engineering is currently investigating this issue. **Radio replacement isn't recommended as it will perform the same.**

POLICY:

Information Only.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.