

Technical Service Bulletin (TSB)

Whistle Noise From Engine Area

REFERENCE:	TSB: 09-015-26 GROUP: 09 - Engine	Date:	July 25, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 - 2027 (B1) Jeep Renegade 2026 - 2027 (M1) Jeep Compass This bulletin applies to vehicles built on or after January 01, 2026 (MDH 0101XX) and on or before June 17, 2026 (MDH 0617XX).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ EE☐ IAP ☒ SA☐ CH NOTE: This bulletin applies to the North America (Mexico only) and South America markets.	
CUSTOMER SYMPTOM:	Customers may comment on the following: Whistle noise from engine compartment.				
CAUSE:	Auxiliary electric water pump				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-141, date of issue July 25, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting for a whistle noise and possibly replacing the auxiliary electric water pump.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
07-52-02-90	Auxiliary Electric Water Pump - Inspect (1 - Introduction)	1 - Engine Repair and Performance	0.2 Hrs.
07-52-02-91	Auxiliary Electric Water Pump - Inspect and Replace (1 - Introduction)	1 - Engine Repair and Performance	1.4 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	2850001427	Auxiliary Electric Water Pump	
(AR)	7092803 - EMEA 68626281AA - Mopar	Coolant OAT 50/50 (cada 100 mL)	Apenas reembolso em garantia

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Start the vehicle.
2. Open the hood and listen for a whistle noise from engine compartment.
3. Was a whistle a noise heard?
 - YES >>> Proceed to [Step 4](#).
 - NO >>> This bulletin has been completed. Use Inspect LOP (07-52-02-90) to close the active RSU.
4. Replace the auxiliary electric water pump. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 1088C16 - Bomba de agua suplementar - remocao/recolocacao. incluso procedimentos (Supplementary water pump - removal/reinstallation. Procedures included).

NOTE: For SA market only, after applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.