



Service Bulletin

Bulletin No.: PIC6548B

Date: July, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip For - Cannot Switch Between Adaptive and Regular Cruise Control or Cruise Control Inoperative After Front Camera Replacement

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Encore GX	2020 - 2026		All	All	All	All
Buick	Envista	2024 - 2026		All	All	All	All
Chevrolet	Trailblazer	2021 - 2026		All	All	All	All
Chevrolet	Trax	2024 - 2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	KSG, TQ5
Condition	Customer may comment that they cannot switch between adaptive and regular cruise or cruise control is inoperative. Customer may also comment that the Intellibeam headlamp feature is also inoperative. These conditions may be present after the front camera module was replaced.
Cause	Front Camera Module was not SPS configured after programming.

Correction

Confirm vehicle will not switch between adaptive cruise and regular cruise by pressing and holding the cruise control cancel button.

If this fails, the technician will need to run the SPS Front Camera configuration.

Version	3
Modified	05/01/2024 - Created. 06/05/2026 - Updated Model Years 07/23/2026 - Updated Model Years

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.