

McLaren Artura Shift Paddle DTCs

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Document Information

Location: Transmission, Steering Wheel

Topic: Shift paddle related DTCs

Condition: Intermittent

Diagnostic Trouble Codes: P08162F, P08162F, P08152F

Measure

If you are presented with a McLaren Arura with a transmission warning message or functional concern with DTCs for shift paddles pre-cog signal erratic have been stored and the paddle adjustment is believed to be at fault **DO NOT** adjust the paddles. Please raise a Technical Request for instruction on how to proceed.

Parts Information

N/A

Repair Time

N/A

Attachments

N/A