



Service Bulletin

Bulletin No.: PIT6002C

Date: July, 2026

PRELIMINARY INFORMATION

Subject: DTC U1521 After Replacing The Headlamp With (TSH or T26) Adaptive Forward Lighting System

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2008 - 2017		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	(TSH or T26) Adaptive Forward Lighting
Condition	DTC U1521 After Replacing The Headlamp With (TSH or T26) Adaptive Forward Lighting.
Cause	Part concern with the new right side headlamp assembly

Correction

If you get an Enclave with (TSH or T26) where the headlamp has been replaced and you get DTC U1521.

There is a concern with the new right side headlamp assembly where after replacing it you will get a U1521 and the Adaptive Forward Lighting will not work.

There is no resolution available, and no updated parts are in development.

This PI will be updated If more information is available.

Version	4
Modified	04/17/2023 - Created on. 02/01/2024 Updated to add note to correction. 04/19/2024 - Updated Correction 07/27/2026 _ Updated Correction

