



Connection offline

Technical Service Bulletin

Transaction No.: 2082648/1

94-26-01 - Windshield Wipers Ghost Operation

Condition

Applicable Vehicles					
VW Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas	2022-2026	All	All	CA_NC000001	CA_TC542862
Atlas Cross Sport	2022-2026	All	All	CA_NC000001	CA_TC231347
Taos	2022-2026	All	All	B2_NM000001	B2_TM013266
Jetta	2022-2026	All	All	BU_NM000001	BU_TM009445
Tiguan	2022-2024	All	All	All	All

Revision Table			
Instance Number	Publish Date	Version Number	Reason for Update
2082648/1	7/7/26	94-26-01	Original Publication

Technical Background

Internal Failure of the wiper spring in the steering column switch assembly.

Production Solution

Production Improvements.

Service

If the customers complaint is that wipers are activated by themselves, replace the steering column switch assembly.



NOTICE

If there is a DTC associated with the complaint follow the DTC test plan. This bulletin does not apply.

Warranty

Information Only.

Required Parts and Tools

Information Only.

Additional Information

© 2026 Volkswagen Group of America, Inc. / Volkswagen Group Canada Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc. / Volkswagen Group Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.