



Connection offline

Vehicle-specific service

Transaction No.: **2079830/4**

01 PSS Engine mounting - noises between 4,000 and 4,200 RPM

Release date: Jul 7, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A7 e quattro	2020 – 2021	All	PR Code: 0K3
A8 e quattro	2021 – 2022		

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised <i>Condition</i> (Updated ETA)
3	06/04/2026	Revised <i>Condition</i> (Updated ETA)
2	02/24/2026	Revised <i>Condition</i> (Updated ETA)

Customer states:

When the engine is at operating temperature, noises (humming/Droning) can be heard from the front area of the vehicle when the engine is running between 4,000 and 4,200 rpms.

Workshop findings:

The complaint can only be reproduced while driving a vehicle with a combustion engine and can be assigned to engine mounting. Engine mountings with part number 4M0199255.**BK/BP/BQ** 4M0199256.**BK/BP/BN** are fitted in the vehicle.

Technical Background

Not applicable.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

If the description matches the customer complaint, do not carry out any further repairs for the time being.

This TSB only applies if engine mountings 4M0199255.**BK/BP/BQ** 4M0199256.**BK/BP/BN** are fitted in the vehicle in question.

A technical solution is currently being implemented. The solution is currently planned to be available in the fourth quarter of 2026.

Note: The target date communicated here is based on planning and is not binding. During the validation, technical and regulatory approval of measures, there may be delays or hindrances in providing the measure throughout the entire process. This must be considered accordingly when communicating with customers.

As part of the process, it is necessary to create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

Replacing parts or attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Additional Information

All part and service references provided in this TSB (**2079830**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.