



Connection offline

Vehicle-specific service

Transaction No.: **2081542/2**

01 PSS Drive System Fault, DTC P119A00 or P119B00 stored in ECM, 3.0L V6 TFSI

Release date: Jul 1, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
S5 (FU), SQ5, and SQ5 Sportback (GU)	2025	All	Engine type: DWVA (3.0L TFSI)
A6 (FN)	2026		

Customer states:

- Drive system fault active in instrument cluster.

Workshop findings:

One or both of following DTCs are stored in the Engine control unit, J623 (address word 0001):

- **P119A00** Fuel pressure sensor Malfunction – symptom 13432 – static/intermittent
- **P119B00** Fuel pressure sensor 2 Malfunction – symptom 17873 – static/intermittent

Technical Background

Software issue (engine control unit, address 0001) with rail high-pressure diagnostics.

Production Solution

Not applicable.

Service

Please postpone repair. A combined software update with the target combined software version 03.11.00/C [KD2* = KD2S] is currently being implemented.

It will be rolled out in stages for the different models and markets. All information about the current schedule and availability of the measure can be found in the central service info 2081477, *00 Service info: central overview of combined software update 03.11.00/C PPC/PPC – KD2**

As part of the process, create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

Replacing parts of attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2409		
Damage Code:	0039		
Labor Operations:	GFF / Guided Functions	0150 0010	See SRT with associated operations
	GFF / Guided Functions	0150 0060	See SRT with associated operations
Claim Comment:	As per TSB 2081542/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2081542**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.