

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
S5 (FU) and SQ5 (GU)	2025	All	Engine Code: DWVA 00A5 – front sensor for driver assistance system			
			Software part number	Software version	Hardware part number	Hardware Version
A6	2026		*85E*.907.217.L*	0250	*85E*.907.217.A*	H18
			85E.907.217.BB	0381	*85E*.907.217.A*	H18
			85E.907.217.N*	0295	*85E*.907.217.A*	H18

Customer states:

- The message “Drive system: fault. Please contact workshop” appears in the instrument cluster.

Workshop findings:

One or more of the following event memory entries are logged in engine control unit J623 (diagnostic address 0001):

- U029400** – Lost Communication With Powertrain Control Monitor Module
- U015100** – Lost Communication With Restraints Control Module

Technical Background

Production Solution

Software optimization with software cluster 6:

A5 (type FU) and Q5 (type GU) from model year 2026 onward.

A6 (type FN) from vehicle production date 02/16/2026 onward.

Service

Please postpone repair. A combined software update with the target combined software version 03.11.00/C [KD2* = KD2S] is currently being implemented.

It will be rolled out in stages for the different models and markets. All information about the current schedule and availability of the measure can be found in the central service info 2081477, *00 Service info: central overview of combined software update 03.11.00/C PPC/PPC – KD2**

As part of the process, create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	GFF/ Guided Functions	0150 0010	See SRT with associated operations
	GFF/ Guided Functions	0150 0010	Labor according to the diagnostic log
Claim Comment:	As per TSB 2082593 /1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2082593**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.