

Technical Service Bulletin (TSB)
Transmission Control Module (TCM) Diagnostic
Trouble Codes (DTCs) Causing Unnecessary
Battery Replacements And Not Resolving Issue

REFERENCE:	TSB: 08-289-26 REV. A GROUP: 08 - Electrical	Date:	July 30, 2026	REVISION:	08-289-26
VEHICLES AFFECTED:	2026 (WL) Jeep Grand Cherokee / Grand Cherokee L 2026 (WS) Wagoneer / Grand Wagoneer 2026 (LB) Dodge Charger			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	N/A - This bulletin was released in error.				
CAUSE:	N/A				

This bulletin supersedes Service Bulletin 08-289-26, dated July 21, 2026, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

DISCUSSION:

This document is no longer available.

POLICY:

Information Only.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.