



TECH TIP

ID No.

Ref. No.

Release Date

TT-26-006

HMS TechAssist Case 111749

7/7/2026

Driving Support Malfunction ABS Light On No Communication

OVERVIEW

Driving Support Malfunction warning and/or ABS light on, communication concerns with the Wabco ABS module, possibly related DTC's too. We have found in some instances, a poor connection or backed out terminal found at the junction located behind the front bumper area. Follow the procedure to inspect the area of concern.

SUBJECT VEHICLES

2022MY to current L-Series trucks equipped with Lane Departure and Collision Mitigation.

WARRANTY TERMS

This TechTip is for information only, it does not imply any warranty

PROCEDURE

Driving Support Malfunction ABS Light On No Communication

PROCEDURE



1. Locate the junction behind the front bumper as shown in the images below.



Driving Support Malfunction ABS Light On No Communication

PROCEDURE

2. Inspect for backed out terminals, loose pins and/or corrosion and repair if found



3. Once repairs are complete, re-evaluate operation