



TECH TIP

ID No.

TT-26-008

Ref. No.

HMM-26-702-F1

Release Date

7/21/2026

Driveshaft Center Bearing Damage

SUBJECT VEHICLES

2022 through 2026 model year Hino L-Series trucks

WARRANTY TERMS

NOTICE: This Technical Tip is provided as technical information and is not authorization for a warrantable repair.

OVERVIEW

If the truck experiences driveshaft center bearing damage or repeated damage, visually inspect the installed position of the center bearing, specifically the relationship between the dust cover and center bearing strap. If the installed position reassembles the photograph below, open a TechAssist case describing the condition/concern and attach an image of the trucks driveline dust cover to center bearing alignment for further direction.

