

 26-01-060H - Loose Transmission Oil Level Plug (Limited Coverage Campaign LA15) (Posted 07.27.26).pdf

Hyundai Motor America (HMA) has launched Limited Coverage Campaign LA15: Loose Transmission Oil Level Plug - Automatic Transmission Replacement.

A. Affected Vehicles:

1. VIN Identification: Use the 'Vehicle Information' screen in WebDCS to verify "Warranty Start Date" and ensure the vehicle is within New Vehicle Limited Warranty (NVLW), observing mileage prior to any repair work.

a. Certain 2025 - 2026MY Sonata (DN8) produced 02/04/2025 - 07/17/2026

i. Built by Hyundai Motor Company ("HMC")

1.

B. Campaign Description:

Certain Sonata (DN8) vehicles may exhibit a transmission oil leak at the bottom of the valve body cover due to a loose oil level plug that could potentially lead to a total failure of the automatic transmission.

2.

3. **Technical Service Bulletin (TSB) 26-01-060H** instructions to inspect the oil level plug and transmission oil level and, if necessary, replace the automatic transmission.

C. Campaign Document:

4. **1. TSB 26-01-060H**

1. a. Available on [Hyundaidealer.com](https://hyundaidealer.com) > Service > Service Programs > HMA Tech Info > Campaign

D. Parts Ordering/Information:

1. Please refer to **Technical Service Bulletin (TSB) 26-01-060H** for parts ordering information.
2. A valid campaign VIN is required for parts ordering for the transmission. Please only order if necessary based on the inspection criteria.

E. Important Notes:

1. Confirm VIN eligibility for campaign via WebDCS. See 'VIN Identification' above.

2. Follow TSB 26-01-060H to perform the service procedure.

3. Submit campaign claim once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers. Thank you for your patience and understanding.

HMA Warranty Campaigns