

RAPID UPDATE

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

Rapid Update 824

Grecale – BCM Parameter Alignment



DATE: August 4 2026

Certain Maserati vehicles listed in MODISCS+ are involved in a Rapid Update to write a parameter of the BCM (Body Control Module) control unit.

VEHICLES INVOLVED: (M182) Grecale MY24**Description**

Due to a manufacturing anomaly, on some vehicles the timing parameter for locking the doors with the keys inside the passenger compartment may not be correctly configured. The function, known as the "**surfer maneuver**", can be selected by the customer and may therefore not be correctly set.

Required Action

Perform the parameter update procedure according to the instructions in the bulletin.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

Please read and review this bulletin first before ordering parts and/or starting the procedure.

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.


Maserati Americas
Aftersales Dept.

Technical Procedure



All images shown in this bulletin are for illustrative purposes only

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Before proceeding, make sure the **engine is OFF**.
3. Connect the 12V battery to the **Battery Maintainer**.
4. Using MD EVO, perform the following procedure: **BCM – Initialization**.



5. Follow the on-screen instructions.
6. Once completed, the vehicle can be released.

Warranty Claim

Please complete the warranty request as follows:

Description	Code
Rapid Update Number	824
Warranty Code	23
Error Code	063
Component Code	8.61.035
Operation Code ▪ SW Update	8.61.035.A (0,20 h)