



Service Bulletin

Bulletin No.: PIC6661

Date: August, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Tail Lights Stay on After Vehicle is Shut Off


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	OPTIQ	2025 - 2027		All	All	All	All

Involved Region or Country	North America
Condition	Customers may comment that tail lights stay on after vehicle is shut off.
Cause	Possibly water intrusion in rear tail lamp connector.

Correction

Technicians are asked to verify if any water intrusion in rear tail lamp connector before following normal SI diagnostics.


See examples below:



7200499



7200497



7200498

If water intrusion is present or corrosion is found, repair or replace affected components per SI instructions, as necessary.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
5481078*	Inspect rear tail lamp connector for water intrusion	0.2 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	08/19/2026 - Created on

