



Service Bulletin

Bulletin No.: PIC6656A

Date: August, 2026

PRELIMINARY INFORMATION

Subject: Rear Brake Pad Noise When in Reverse

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	OPTIQ	2025 - 2027		All	All	All	All
Chevrolet	EQUINOX EV	2024 - 2027		All	All	All	All

Involved Region or Country	North America
Condition	Customers may mention that there is rear brake pad noise when in reverse. This could occur in humid or colder weather conditions.
Cause	Undetermined at this time.

Correction

Engineering is currently investigating.

In the meantime, please advise the customer that they can continue to drive their vehicle.

The PI will be updated or replaced with TSB once a determination has been made.

Version	2
Modified	07/24/2026 - Created on 08/17/2026 - Updated Models

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.