



# VOLUNTARY SERVICE CAMPAIGN

|                 |            |                 |
|-----------------|------------|-----------------|
| Classification: | Reference: | Date:           |
| EL05-030A       | NTB05-086A | August 24, 2026 |

## VOLUNTARY SERVICE CAMPAIGN BODY CONTROL MODULE SUB-HARNESS

**CAMPAIGN I.D. #:** P5234

**APPLIED VEHICLES:** 2004-05 Titan (A60)  
2004-05 Armada (TA60)  
2005 Frontier (D40)  
2005 Pathfinder (R51)  
2005 Xterra (N50)

**APPLIED VINS:** Titan King Cab: 1N6\*A06\*\*4N500014-593471  
Titan King Cab: 1N6\*A06\*\*5N500006-547508  
Titan Crew Cab: 1N6\*A07\*\*4N055132-593472  
Titan Crew Cab: 1N6\*A07\*\*5N500000-547507  
Armada: 5N1\*A08\*\*4N057073-747082  
Armada: 5N1\*A08\*\*5N700000-725222  
Frontier King Cab: 1N6\*D06\*\*5C400026-437197  
Frontier Crew Cab: 1N6\*D07\*\*5C400012-437203  
Pathfinder: 5N1\*R18\*\*5C700001-748937  
Xterra: 5N1\*N08\*\*5C600000-621507

### **Voluntary Service Campaign ID # P5234 is no longer active.**

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P5234.
- Discard all previous versions of NTB05-086.

### AMENDMENT HISTORY

| PUBLISHED DATE     | REFERENCE  | DESCRIPTION                 |
|--------------------|------------|-----------------------------|
| September 22, 2005 | NTB05-086  | Original bulletin published |
| August 24, 2026    | NTB05-086A | Amended to sunset           |