

-  26-BE-022 - Clock Spring (Warranty Extension TXXA) (posted 08.24.26).pdf
-  Warranty Extension TXXA - Clock Spring - Dealer Notification (posted 08.24.26).pdf

Hyundai Motor America (HMA) has re-launched Warranty Extension TXXA: Clock Spring - Diagnostic Trouble Codes (DTC) B134600 & B148100.

This revised Technical Service Bulletin (TSB) includes the latest revisions:

- - Clarify the production date range for each model (page 1)
- Update warranty information table to remove 'inspection' (page 2)
- Updates to the service procedure (page 2)

A. Warranty Extension Description:

The warranty coverage for the clock spring has been extended to 15 years with unlimited mileage from the date of original retail delivery or date of first use. Refer to the warranty and service parts information outlined in this bulletin whenever clock spring replacement is required. The DTCs associated with this bulletin are:

- B134600 – Driver Airbag (DAB) – 1st Stage – Resistance High
- B148100 – Driver Air Bag 2nd stage (DAB) - High

Technical Service Bulletin (TSB) 26-BE-022H provides instructions to scan for DTCs B134600 & B148100 and if necessary, replace the clock spring assembly .

B. Affected Vehicles:

1. VIN Identification: Use the 'Vehicle Information' screen in WebDCS to verify "Warranty Start Date" and ensure the vehicle is within the extended warranty coverage, observing time prior to any repair work.

- a. 2011-2013MY Sonata (YFA) produced from 12/11/2009 - 06/20/2012
- b. 2011-2014MY Sonata Hybrid (YF HEV) produced from 12/02/2010 - 04/02/2014
- c. 2011-2014MY Elantra (MD) produced from 11/12/2010 - 10/30/2013
- d. 2011-2014MY Elantra (UD) produced from 10/29/2010 - 11/27/2013
- e. 2011-2014MY Elantra Coupe (JK) produced from 03/16/2012 - 08/26/2013

C. Parts Information

1. Please refer to TSB 26-BE-022H for the latest parts information regarding the clock spring assembly.

D. Warranty Extension Documents:

1. TSB 26-BE-022H; supersedes TSB 17-BE-004-1

- a. HyundaiDealer.com > Service > Service Programs > Hyundai Tech Info > TSB

2. Dealer Notification; Supersedes existing document

E. Action Required:

1. Confirm VIN eligibility for campaign via WebDCS. See 'VIN Identification' above.
2. **Follow TSB 26-BE-022H** for the service procedure to scan for DTCs B134600 & B148100 and if necessary, replace the clock spring assembly.
3. **Submit warranty claim** once the service procedure is completed.

We appreciate your continued partnership and commitment to our Hyundai customers.

Thank you for your patience and understanding.