

2018-22 Accord Center Display Changes Screens Without User Input

AFFECTED VEHICLES

Year	Model	Trim Level
2018-22	Accord	All

BACKGROUND

Customers may report that the center display unit changes screens on its own, registers unintended inputs, or operates erratically without user interaction. The condition may be more noticeable when vehicle interior temperatures are elevated.

TECH LINE NOTE

Tech Line is aware of a false (ghost/phantom) touch condition affecting the center display unit. The center display unit may register unintended inputs, change screens without user interaction, or exhibit erratic operation. The condition may be more prevalent at elevated interior temperatures. A permanent countermeasure is currently under development.

INVESTIGATION STATUS

A supplier investigation is currently in progress to identify the root cause and develop a permanent countermeasure.

PROBABLE CAUSE

A manufacturing-related issue within the center display unit that may be aggravated by heat buildup in the center display unit.

REPAIR INFORMATION

Do not replace center display unit or components for this concern unless directed by Tech Line or current service information.