

47X/49X Twin Steer Equalizer Beam Bushing Wear

COMMUNICATION:

FIELD SOLUTION: Fix as fail

PUBLISH DATE: N/A

TOPIC BACKGROUND:



PRIMARY EFFECT:

- 47X/49X twin steer front suspension equalizer bushings are wearing/tearing at low mileages. Symptom reported as audible knocking noise during turning events.
- Equalizer beam bushing used in tandem taperleaf or flat leaf front suspensions.

AFFECTED MODELS:

- 47X/49X Twin Steer

VISUALIZATION:



PROGRESS UPDATES:

- AM pricing finalized with bushing supplier Reyco for correct replacement bushing. July 2026, part reactivated in AM system and available for orders.
- Engineering working with supplier.

TOPIC RESOLUTION

PRODUCTION CHANGEOVER WEEK/MONTH:

- N/A
- No change to production until corrective action at supplier complete (see below resolution path)

RESOLUTION:

- Two resolution paths in process:
 - New design bushing with improved performance
 - Corrective action at beam assembly supplier where the bushing is installed