

GPOP - Issue Review System

Part Number: 05281614A\$, 68570195A\$, 68604560A\$

Part Description: Turbocharger Kit

Issue Description: Please note that many turbo components are serviceable separately and full turbo replacement may not be required. If the turbo is being inspected for:
Noise/Rattle:
Inspect heat shield fasteners for looseness and check the wastegate actuator/linkage for binding. The actuator kit is serviced separately. Oil Leak:
Inspect the turbo oil feed O-ring area for leaks. O-ring is serviced separately.