

WTL3 Workshop Campaign – Replace roof module seal

WTL3 Workshop Campaign - Replace roof module seal

ID Number	WTL3
Affected Model(s)	Cayenne Electric (X1A)
Affected Model Year(s)	2026
VIN List	Attached below
Number of Affected Vehicles	83
Issue Description	On the affected vehicles, there is a possibility that the front left and right roof module seal was not applied correctly. As a result, the seal is not durable and can partially detach. Over the service life of the vehicle, this may lead to leaks in the area of the roof module. For this reason, the roof module seal must be replaced.
What should Porsche Centers do?	Please arrange for this action to be carried out in the affected vehicles during the next workshop visit. As of the time of this posting (8/21/26) the repair is immediately available. Vehicles that are still present before delivery to the customer should be processed as a priority.
Parts Status	Status 1 - Order via PPL as needed
Technical Information	WTL3

Required parts

PAB877459B	Seal for sliding roof	1 piece(s)	No
PAB898955	Seating of fastening screws	1 piece(s)	No

Vehicles that are still present before delivery to the customer should be processed as a priority.

Warranty processing

Validity:

The present workshop campaign is carried out by the date maintained in PCSS and then closed.
Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Number	WTL3 66 000
Repair Code	1
Labor time	90 TU

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Attachments

1. [VIN_List_Report_WTL3_2026-08-21_V4.xlsx](#)