

RSB-52-26-001-1: Replace R2 Roof Glass

Rivian is launching a technical service bulletin for some model year 2027 R2 vehicles with roof glass that does not provide optimal protection from high solar loads on sunny days. Upon customer complaint of high interior temperatures from sun exposure through the roof glass, Rivian will replace the roof glass with a version that reduces solar load.

Document Type	Technical Service Bulletin
Date	August 27, 2026
Affected Region(s)	USA
Affected Model(s)	R2
Model Year(s)	2027
Approximate Build Dates	April 2026 - May 2026
Note: Refer to the TSB Guide Dashboard to determine if this document applies to a specific vehicle.	
Vehicle System	52 - Body
Rivian Reference Number	FSAM-1836

Required Parts

Part Number	Quantity	Engineering Name	Service Name/Notes
PT01711360-B	1	GLASS SUB-ASSY - ROOFGLOSS SUB-ASSY - ROOF	Glass, Roof

Attention:

The parts listed in this table are only for unique steps that are called out in this bulletin. Some sections of this bulletin might refer to Service Manual procedures which require additional parts. Always review the bulletin and all potentially related Service Manual procedures before ordering parts and beginning work.

Procedure

1. Replace: Glass, Roof (refer to service manual procedure 523430010).
2. Reinstall all components that were removed for access and replace all non-reusable components. Refer to the service manual procedures referenced in this document for additional component reusability information and torque specifications.

Labor Codes

Labor Code	Description
RSB522600100	RSB-52-26-001-1 not applicable
RSB522600101	Remove and replace roof glass
Contact DiagnosticContentFeedback@rivian.com regarding labor codes and document content.	

[Download a PDF copy of this document.](#)