

Reference	SSM76487
Models	Defender / L663
Title	Air Conditioning Inoperative / Intermittent Operation
Category	Electrical
Last modified	20-Aug-2026 12:17:00
Symptom	208000 Climate Control

Content**Model / Model Year / Derivative**

Land Rover Defender / 20MY onwards / LHD Only

Situation:

JLR Engineering investigations have identified reports no air flow or intermittent air flow blowing from vents and Diagnostic Trouble Code (DTC) B149A-13 - 'Blower Motor - Circuit open' stored in the HVAC module.

Cause:

The cause is currently under investigation. Following the guidance within this SSM will assist Engineering with their investigations.

Action:

Confirm DTC B149A-13 is present, if yes follow the service request below.

Service Request:

To assist Engineering with determining the root cause, follow the below actions:

Replace the complete HVAC assembly (LR171248 blower assembly)

Raise an Electronic Product Quality Report (EPQR), which must include the below information:

- Reference to P393713 (Project number)
- Reference to this SSM (SSM76487)
- Confirmation that the removed part(s), are being retained.

(Ref 00393713 / 3027)

anBhdHRIcnM7MjAyNi0wOC0yMVQzMjczNz00S44MDRaOzEwOC41NC4yMjMjwOw==