

Reference	SSM76500
Models	New Range Rover / L460
Title	Unpleasant Odour Coming From Interior Of The Vehicle
Category	Body
Last modified	28-Aug-2026 17:25:00
Symptom	101000 Seating

Content

Model / Model Year / Derivative

Range Rover / 22MY Onwards / SE vehicles with Windsor perforated Perlino leather interior.

Situation:

JLR Engineering investigations have found customer reports of an unpleasant odour coming from the vehicle interior.

Cause:

The anti-soil topcoat treatment applied to the seat material during manufacture.

Action:

Refer to the Service Request below.

Service Request:

1. Start a new diagnostic workflow and select one of the following symptoms:

- Body > Unpleasant Smell/Odour From Interior
- Body > Seats > Unpleasant Smell/Odour

2. Follow the workflow and complete any on-screen instructions.

(Ref 00394611/7368)

anBhdHRIcnM7MjAyNi0wOC0zMVQzMjc0Mjc0Ny4xNjFzEwOC41NC4yMjMjMjwOw==