



Spartan Fire, LLC

Campaign Service Bulletin
CSB26-150-004

DATE: 8/20/2026

APPLIES TO: This service bulletin applies to certain model year 2026 Gladiator and Metro Star model emergency response chassis cabs built between April 2026 and June 2026.

CONDITION: Incorrect label was installed inside the front grill.

CORRECTION: Install correct label to the inside of the front grill.

LABOR ALLOCATION: 0.5 hours

CLASSIFICATION: V3

PARTS NEEDED: Supplied with Notification

<u>QTY</u>	<u>Part Number</u>	<u>Description</u>
1	4157-EE2-001	Label-warning, non-step surface

GENERAL INSTRUCTIONS:

Thoroughly review entire service bulletin before starting work. If there are questions or concerns with steps defined in this service bulletin, contact Spartan Fire, LLC. Customer & Product Support Group.

All applicable industry safety standards must be followed when performing work identified in this procedure.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



Spartan Fire, LLC

Campaign Service Bulletin
CSB26-150-004

STEP-BY-STEP INSTRUCTIONS

- 1) Release grill latches and lower front grill.
- 2) Locate incorrect label attached to inner surface of the grill.
(See incorrect label in figure 2.1)



Figure 2.1

- 3) Remove the label and dispose of label. An adhesive remover may be required to adequately remove the label. Use caution to avoid getting any remover on the highly visible surfaces of the grill that could result in discoloration.

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.



Spartan Fire, LLC

Campaign Service Bulletin
CSB26-150-004

- 4) Apply the new label part number 4157-EE2-001 as shown in Figure 3.1.



Figure 3.1

Service Bulletins are intended for use by Professional Technicians only. They are written to guide Professional Technicians in performing service to vehicles of specific nature in conjunction with industry standards. Professional Technicians should be appropriately trained on industry standards and have the tools and equipment to perform procedures safely and properly.