



Service Bulletin

Bulletin No.: PIT6546

Date: September, 2026

PRELIMINARY INFORMATION

Subject: SES MIL ECM Setting P0494

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Envision	2026		All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a Malfunction Indicator lamp illuminated and the technician may find DTC P0494 Cooling fan speed too low.
Cause	Engineering is currently investigating.

Correction

Do not replace the cooling fan for this DTC. Engineering is currently investigating. The PI will be updated or replaced with TSB once a determination has been made. Clear the DTC and release the vehicle to the customer.

Version	1
Modified	09/02/2026 Created on

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



**WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION**

Copyright 2026 General Motors. All Rights Reserved.