



STAR ONLINE PUBLICATION



Case Number: S2623000055

Release Date: September 2026

Models Affected:
2026 – 2027 Dodge Charger (LB)

Symptom/Vehicle Issue: Front Fascia Paint Peeling at Interface to Fender. Caused When There is no Gap Between Fender And Fascia, And the Fender Has a Metal Deformation on it.

Discussion/Repair Procedure: Remove the front fascia. Sand/repaint the affected area (see Fig 1). Properly repair any metal deformations that align with where the paint is peeling. Reinstall all components following proper procedures outlined in Service Library.




Fig 1

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous case details that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.