

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title		Ref. No.	
Front bumper - gap		TJ 37553.1.0	
Issuer (Dept.)		Issue Date	Status Date
Technical Service		9/3/26	9/15/26
Car Market	Partner	Function Group	
United States and Canada	3 US 7510 Volvo Car USA	8611	
Function Description		Page	
Bumper, front		Page 1 of 6	

Attachment

File Name	File Size
I-522169-4_1_1_en-US.pdf	2.9695 MB

DESCRIPTION:

If the vehicle has an abnormal gap between bumper and lower mesh follow advice under "Service".

CSC Customer Symptom Codes

Code	Description
L2	Bumper/Fits poorly
U5	Bumper/Other bumper problems

DTC Diagnostic Trouble Codes

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2025-2027		-	202446-202634

SERVICE:

Use OP number 86103-2 to remove the bumper and the method described in TJI-522169-4_1_1_en-US.pdf to reinforce.

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ. Please note that fault tracing is not eligible for separate reimbursement under this TJ. Any fault tracing VST OP numbers will be rejected.
Note that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
98813-2	General Reimbursement acc. to TJ



Technical Journal 37553.1.0

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8611.

To view TJ attachments continue to next page. This TJ has one attachment.



Volvo Car Customer Service

TJ Instruction VCC-522169-4

Title	Cover bumper, repair	Page	1 (4)
Action	Reconditioning	Operation number:	98813-2

Issue	Date	Reason
1	2025-10	First issue

Affected vehicles

Model year	Model
2025	XC90 (16-)

Materials

Materials	Qty.	Part No.	Notes
Cable tie	10	989098	


Removal

Note! Removal steps in this procedure may contain installation details.


Disassemble cover bumper front 2024W46- , refer to:


Removal, replacement and installation
8 - Body and interior
86 - Bumpers and mudflaps
861 - bumper with suspension and damping

Remove the cable harness.




Release the catches.
Remove the marked part.





Use new clips.



Use new clips.

Installation

To install, reverse the removal procedure.