U.S. Department of Transportation

National Highway Traffic Safety Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire

To Report Vehicle Safety Defects
1-888-DASH-2-DOT
(1-888-327-4236)
INTERNET:www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 100148

Date Received	Repository
AUG 27 2010 08-JUL-2010	☐
	Reference No. 10342035

OWNER INFORMATION (Type or Print)

Name	[redacted]	Daytime Telephone Number	E-mail Address
Address	[redacted]	[redacted]	NONE
City GREENSBURG	State PA	Zip Code [redacted]	Evening Telephone Number SAME

The information you provide will be used to identify potential safety-related defects. We may share your information with the applicable vehicle manufacturer during an investigation or recall in accordance with the routine uses described in the agency's Privacy Act notice. See 49 FR 53971 (Sep. 3, 2004).

VEHICLE INFORMATION

17 digit Vehicle Identification Number Located at bottom of windshield on driver's side	Make	Model	Model Year
1GTEK14V0X[redacted]	GMC	SIERRA 1500	1999

Date Purchased	Dealer's Name and Telephone Number			Engine:	Fuel Type:
30 APR 07	HILLVIEW MOTORS INC. 724-834-8460			No: Cylinders 8	GAS
Original Owner ☐	Dealer's City GREENSBURG	State PA	Zip Code 15601		

Transmission Type		Powertrain	Multiple Failure:	Incident Date(s)
AUTO	☒ Antilock Brakes ☒ Cruise Control	4WD	NO	29-JUL-2008

FAILED COMPONENT(S)/PART(S) INFORMATION

Vehicle Component Code: 030000 SERVICE BRAKES, HYDRAULIC	Failure Mileage	Failure Speed
	79686	45

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A TIRE FAILURE

Tire Make	Tire Model (Name or Number)	Tire Size (Example P215/65R15)
DOT No. (Example: DOTMAL9ABC036)	☐ Original Equipment ☐ Prior Repair	Failure Location:
Tire Component Code		Tire Failure Type:

ADDITIONAL ITEMS TO BE COMPLETED WHEN REPORTING A CHILD SEAT FAILURE

Make:	Date Manufactured:	Model No./Name:
Seat Type:	Installation System:	
Child Seat Component Code:	Failed Part:	

APPLICABLE INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies).)

Crash	Fire	Number of Persons Injured	Number of Deaths	Reported to Police
☐ Yes ☒ No	☐ Yes ☒ No	0	0	N

Narrative Description of Incident(S), Crash(es), and Injury(ies).
Please describe (1) events leading up to the failure, (2) failure and its consequences, and (3) what was done to correct the failure; i.e, parts repaired or replaced (and if old part is available).

TL*THE CONTACT OWNS A 1999 GMC SIERRA 1500. WHILE DRIVING APPROXIMATELY 45 MPH THE CONTACT APPLIED THE BRAKES AND THE BRAKE LINE THE LEFT FRONT AND RIGHT REAR WHEEL EXPLODED. HE STATED THAT THE BRAKE PEDAL EXTENDED TO THE FLOOR. HE CAREFULLY DROVE THE VEHICLE TO HIS RESIDENCE. THE VEHICLE WAS TOWED TO THE MECHANIC WHERE IT WAS PURCHASED. THE MECHANIC REPLACED ~~THE FRONT CALIPERS AND~~ BOTH LINES TO THE MASTER CYLINDER ~~WITHIN~~ THE ABS UNIT. THE FAILURE MILEAGE WAS 79,686 AND THE CURRENT MILEAGE WAS 80,058. AND

Include, if available: Police/Fire Department Report, Photos, and Repair Invoice. ATTACH ADDITIONAL SHEETS IF NECESSARY

CUSTOMER #: BJ12842

88445

INVOICE

PAGE 1

CHRYSLER Jeep DODGE

HILLVIEW MOTORS Inc.

Route 30 East
Greensburg, PA 15601
(724) 834-8440
(800) 686-4455
Fax (724) 834-4040
www.hillviewmotors.com

[redacted]

GREENSBURG, PA [redacted]
HOME: [redacted] CONT:N/A
BUS: CELL:

SERVICE ADVISOR: 108 BRIAN J HALKO

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
GOLD	99	GMC 1500	1GTEK14V0XE[redacted]	[redacted]	79686/79686	

DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
30APR07 DD			20:00 29JUL08		80.00	CASH	05AUG08

R.O. OPENED	READY	OPTIONS:
29JUL08	05AUG08	STK:BJ12842 DLR:23468

LINE	OPCODE	TECH	TYPE	HOURS		LIST	NET	TOTAL
A	CUST STATES NO BRAKES							
	99	DIO			REPLACED A SECTION ON LINE TO BOTH FRONT CALIPERS AND BOTH LINES FROM THE MASTER CYL TO THE ABS UNIT			
			43	CJ	9.40		564.00	564.00
	16	3400			TUBING	1.63	1.63	26.08
	2	121004			FITTINGS	0.64	0.64	1.28
	1	123300			UNION	2.07	2.07	2.07
	1	85032			BR FLUID	11.37	11.37	11.37

PARTS: 40.80 LABOR: 564.00 OTHER: 0.00 TOTAL LINE A: 604.80

****

NHTSA # 10364-2035

PAID
AUG 05 2008
DISC

Regulators to probe brake failure in Chevy, GMC trucks

The National Highway Traffic Safety Administration started a preliminary investigation into brake failure in 6 million older-model Chevrolet and GMC full-size pickup trucks. The agency is looking at whether corrosion caused by the use of salt in snowy and icy conditions in Northern states is damaging brake controls. GM said it is cooperating in the investigation. The probe is in response to a motorist complaint of sudden loss of brake power and a longer-than-expected stopping distance after a corroded brake line burst. NHTSA has received 110 complaints from drivers of 1999 through 2003 model Chevrolet and GMC C/K series pickup trucks and sport utility vehicles.

CHRYSLER

CHRYSLER FIVE STAR DEALER

Service and Parts Hours

Mon., Wed., Thur., and Fri.
8:00am - 5:00pm
Tues.
8:00am - 8:00pm

* ALL MAJOR CREDIT CARDS ACCEPTED
* Personal Checks accepted with approval

THANK YOU FOR YOUR BUSINESS!

* Full Service Body Shop For All Of Your Collision Need
* Shuttle Services Available
* Early Bird Drop
* 24 Hour Towing 800-805-8067

DESCRIPTION	TOTALS
LABOR AMOUNT	564.00
PARTS AMOUNT	40.80
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	0.00
TOTAL CHARGES	604.80
LESS INSURANCE	0.00
SALES TAX	36.29
PLEASE PAY THIS AMOUNT	641.09

CUSTOMER COPY