NVS-200

CL-10533560-2862

INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C . 552(B)(6)

June 12, 2013 JUL 31 2013

No photo enclosed

Mr. Ludwig Willisch
Chief Executive Officer and President
BMW of North America
300 Chestnut Ridge Rd.
Woodcliff Lake, NJ 07675

RE: 2006 750 Li BMW Front Passenger Seat Separation in the Back

Dear Mr. Willisch:

I address his correspondence to your attention about the above-referenced vehicle. Recently while washing the vehicle, I observed the front passenger seat in the back has separated. I have enclosed a photograph for your review.

This vehicle is gently utilized as I am the only individual in and out of it daily. I drive it may be for a total of 10 miles a day to meet my carpool. I do not have any children. In essence, it is just myself in the vehicle.

I was totally astonished when I observed this separation as this vehicle is utilized very little I have been a loyal BMW owner for ten (10) years – three different BMW models. I have never witnessed this in any of my vehicles.

If you have any questions or require clarification, please feel free to address any correspondence to my attention at: [redacted] N.W., Washington, DC 20001, email [redacted]

Thank you in advance for your attention to this disturbing situation.

Sincerely,

[redacted]

cc: US Department of Transportation
1200 New Jersey Ave, SE
Washington DC 20590.

NHTSA Headquarters
1200 New Jersey Avenue, SE
West Building
Washington, DC 20590

NAM
73113
SMP

[redacted]
Woodbridge, VA[redacted]

CAPITAL DISTRICT [illegible]

12 JUN 2013 PM 2 L

Equality
FOREVER

W96-432

US Department of Transportation
1200 New Jersey Ave, SE
Washington DC 20590.

20590