INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Z50 - LEFT FRONT SEAT ADJUSTER ASSEMBLY - CRACKED WELD



SEAT ADJUSTER ASSEMBLY
WELD CRACK LOCATRION



Code-PNC	Desc-PNC	VIN	Model-Year	Code-NML-Prod	Code-NNA-Model	Num-Eng-Serial	Color-Ext	Color-Int
87653	SLIDE ASS'Y	JN8AZ08T05W[redacted]	2005	Z50	07215	VQ35-374614	KY0	G
87653	SLIDE ASS'Y	JN8AZ08T05W[redacted]	2005	Z50	07215	VQ35-374614	KY0	G
87653	SLIDE ASS'Y	JN8AZ08T05W[redacted]	2005	Z50	07315	VQ35-631361	KH3	G
87653	SLIDE ASS'Y	JN8AZ08T05W[redacted]	2005	Z50	07415	VQ35-639916	AX5	G
87653	SLIDE ASS'Y	JN8AZ08T15W[redacted]	2005	Z50	07415	VQ35-351744	BW9	C
87653	SLIDE ASS'Y	JN8AZ08T15W[redacted]	2005	Z50	07215	VQ35-383260	KH3	G
87653	SLIDE ASS'Y	JN8AZ08T15W[redacted]	2005	Z50	07415	VQ35-400485	K21	G
87653	SLIDE ASS'Y	JN8AZ08T15W[redacted]	2005	Z50	07415	VQ35-437196	KY0	G
87653	SLIDE ASS'Y	JN8AZ08T25W[redacted]	2005	Z50	07215	VQ35-394012	KY0	G
87653	SLIDE ASS'Y	JN8AZ08T25W[redacted]	2005	Z50	07215	VQ35-422444	KY0	G
87653	SLIDE ASS'Y	JN8AZ08T25W[redacted]	2005	Z50	07415	VQ35-405361	KY0	G
87653	SLIDE ASS'Y	JN8AZ08T25W[redacted]	2005	Z50	07215	VQ35-481832	KY0	G
87653	SLIDE ASS'Y	JN8AZ08T25W[redacted]	2005	Z50	07415	VQ35-525950	KH3	G
87653	SLIDE ASS'Y	JN8AZ08T35W[redacted]	2005	Z50	07215	VQ35-379651	KH3	G
87653	SLIDE ASS'Y	JN8AZ08T35W[redacted]	2005	Z50	07215	VQ35-379651	KH3	G

87653	SLIDE ASS'Y	JN8AZ08T35W[redacted]	2005	Z50	07415	VQ35-480477 KH3	G
87653	SLIDE ASS'Y	JN8AZ08T35W[redacted]	2005	Z50	07415	VQ35-480477 KH3	G
87653	SLIDE ASS'Y	JN8AZ08T35W[redacted]	2005	Z50	07415	VQ35-518411 BW9	C
87653	SLIDE ASS'Y	JN8AZ08T35W[redacted]	2005	Z50	07415	VQ35-563758 KY0	G
87653	SLIDE ASS'Y	JN8AZ08T35W[redacted]	2005	Z50	07415	VQ35-618980 K21	G
87653	SLIDE ASS'Y	JN8AZ08T55W[redacted]	2005	Z50	07215	VQ35-527438 QX1	C
87653	SLIDE ASS'Y	JN8AZ08T65W[redacted]	2005	Z50	07415	VQ35-481801 R10	R
87653	SLIDE ASS'Y	JN8AZ08T75W[redacted]	2005	Z50	07415	VQ35-312138 QX1	C
87653	SLIDE ASS'Y	JN8AZ08T75W[redacted]	2005	Z50	07415	VQ35-537853 QX1	C
87653	SLIDE ASS'Y	JN8AZ08T75W[redacted]	2005	Z50	07215	VQ35-545388 EY0	C
87653	SLIDE ASS'Y	JN8AZ08T75W[redacted]	2005	Z50	07215	VQ35-545473 QX1	C
87653	SLIDE ASS'Y	JN8AZ08T75W[redacted]	2005	Z50	07215	VQ35-589060 KH3	C
87653	SLIDE ASS'Y	JN8AZ08T75W[redacted]	2005	Z50	07215	VQ35-589060 KH3	C
87653	SLIDE ASS'Y	JN8AZ08T85W[redacted]	2005	Z50	07415	VQ35-334105 R10	G
87653	SLIDE ASS'Y	JN8AZ08T85W[redacted]	2005	Z50	07415	VQ35-334105 R10	G
87653	SLIDE ASS'Y	JN8AZ08T85W[redacted]	2005	Z50	07415	VQ35-418036 QX1	C
87653	SLIDE ASS'Y	JN8AZ08T85W[redacted]	2005	Z50	07415	VQ35-634376 QX1	C
87653	SLIDE ASS'Y	JN8AZ08T95W[redacted]	2005	Z50	07215	VQ35-441522 AX5	G
87653	SLIDE ASS'Y	JN8AZ08T95W[redacted]	2005	Z50	07215	VQ35-447030 KY0	G

87653	SLIDE ASS'Y	JN8AZ08T95W[redacted]	2005	Z50	07215	VQ35-555883 KH3	C
87653	SLIDE ASS'Y	JN8AZ08W05W[redacted]	2005	Z50	07815	VQ35-428478 K21	G
87653	SLIDE ASS'Y	JN8AZ08W05W[redacted]	2005	Z50	07815	VQ35-428478 K21	G
87653	SLIDE ASS'Y	JN8AZ08W05W[redacted]	2005	Z50	07815	VQ35-428478 K21	G
87653	SLIDE ASS'Y	JN8AZ08W05W[redacted]	2005	Z50	07815	VQ35-645953 KY0	G
87653	SLIDE ASS'Y	JN8AZ08W15W[redacted]	2005	Z50	07815	VQ35-352901 AX5	G
87653	SLIDE ASS'Y	JN8AZ08W15W[redacted]	2005	Z50	07815	VQ35-393486 BW9	C
87653	SLIDE ASS'Y	JN8AZ08W15W[redacted]	2005	Z50	07815	VQ35-393486 BW9	C
87653	SLIDE ASS'Y	JN8AZ08W15W[redacted]	2005	Z50	07815	VQ35-433358 QX1	C
87653	SLIDE ASS'Y	JN8AZ08W15W[redacted]	2005	Z50	07615	VQ35-528695 KH3	G
87653	SLIDE ASS'Y	JN8AZ08W25W[redacted]	2005	Z50	07715	VQ35-345437 BW9	C
87653	SLIDE ASS'Y	JN8AZ08W25W[redacted]	2005	Z50	07815	VQ35-378940 K21	G
87653	SLIDE ASS'Y	JN8AZ08W25W[redacted]	2005	Z50	07815	VQ35-406156 KH3	G
87653	SLIDE ASS'Y	JN8AZ08W25W[redacted]	2005	Z50	07715	VQ35-396733 K21	G
87653	SLIDE ASS'Y	JN8AZ08W25W[redacted]	2005	Z50	07815	VQ35-441403 AX5	C

87653	SLIDE ASS'Y	JN8AZ08W25W[redacted]	2005	Z50	07815	VQ35-441403	AX5	C
87653	SLIDE ASS'Y	JN8AZ08W35W[redacted]	2005	Z50	07615	VQ35-390465	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W35W[redacted]	2005	Z50	07815	VQ35-393276	BW9	C
87653	SLIDE ASS'Y	JN8AZ08W35W[redacted]	2005	Z50	07815	VQ35-393276	BW9	C
87653	SLIDE ASS'Y	JN8AZ08W35W[redacted]	2005	Z50	07815	VQ35-421697	KY0	G
87653	SLIDE ASS'Y	JN8AZ08W35W[redacted]	2005	Z50	07815	VQ35-454925	BW9	C
87653	SLIDE ASS'Y	JN8AZ08W35W[redacted]	2005	Z50	07815	VQ35-517465	EY0	C
87653	SLIDE ASS'Y	JN8AZ08W45W[redacted]	2005	Z50	07815	VQ35-338157	K21	G
87653	SLIDE ASS'Y	JN8AZ08W45W[redacted]	2005	Z50	07815	VQ35-370257	AX5	C
87653	SLIDE ASS'Y	JN8AZ08W45W[redacted]	2005	Z50	07815	VQ35-370257	AX5	C
87653	SLIDE ASS'Y	JN8AZ08W45W[redacted]	2005	Z50	07815	VQ35-370257	AX5	C
87653	SLIDE ASS'Y	JN8AZ08W45W[redacted]	2005	Z50	07815	VQ35-438487	R10	G
87653	SLIDE ASS'Y	JN8AZ08W45W[redacted]	2005	Z50	07815	VQ35-453342	BW9	G
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07715	VQ35-284561	K21	R
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07815	VQ35-342110	KY0	G
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07815	VQ35-352637	KH3	G
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07815	VQ35-376596	K21	G
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07615	VQ35-316016	KY0	G
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07615	VQ35-418230	AX5	C
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07715	VQ35-420391	KH3	G
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07815	VQ35-438766	K21	C
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07815	VQ35-476363	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W55W[redacted]	2005	Z50	07815	VQ35-480031	K21	G
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-339015	KY0	G

87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-348991 EY0	C
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-348991 EY0	C
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-408818 KH3	C
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-408818 KH3	C
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-430484 KY0	C
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-433633 R10	G
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07815	VQ35-433633 R10	G
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07615	VQ35-468047 QX1	C
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07615	VQ35-468047 QX1	C
87653	SLIDE ASS'Y	JN8AZ08W65W[redacted]	2005	Z50	07615	VQ35-553019 EY0	C
87653	SLIDE ASS'Y	JN8AZ08W75W[redacted]	2005	Z50	07815	VQ35-390138 QX1	C
87653	SLIDE ASS'Y	JN8AZ08W75W[redacted]	2005	Z50	07815	VQ35-372785 AX5	C
87653	SLIDE ASS'Y	JN8AZ08W75W[redacted]	2005	Z50	07815	VQ35-431145 KH3	C
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07815	VQ35-332668 KY0	G
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07715	VQ35-358494 K21	R
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07815	VQ35-394894 KY0	G
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07815	VQ35-423631 BW9	C
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07815	VQ35-443268 K21	G
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07715	VQ35-443312 K21	G
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07815	VQ35-534095 K21	G
87653	SLIDE ASS'Y	JN8AZ08W85W[redacted]	2005	Z50	07815	VQ35-536871 BW9	C

87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-332257	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-347996	K21	C
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-352262	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-374098	K21	G
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07615	VQ35-380772	EY0	C
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-426277	EY0	C
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-426277	EY0	C
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-449822	KH3	C
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-488976	BW9	G
Incident part collected and sent to NML	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07615	VQ35-536474	KY0	G
87653	SLIDE ASS'Y	JN8AZ08W95W[redacted]	2005	Z50	07815	VQ35-589338	K21	G
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-380106	R10	G
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-380636	KH3	G
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-391743	K21	G
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-391743	K21	G
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-367148	K21	G
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-401315	KY0	G
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-390902	KH3	C
87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-566968	KY0	G

87653	SLIDE ASS'Y	JN8AZ08WX5W[redacted]	2005	Z50	07815	VQ35-625936	AX5	G

Code-Plant	Date-Mfg	Date-In-Svc	Code-AssDist	Code-Acc	POE	Code-SellRegion	Code-SellDlr	St-SellDlr
W	10/28/2004	12/31/2004	US	C03,L92,M94,I	26	26	3717	NY
W	10/28/2004	12/31/2004	US	C03,L92,M94,I	26	26	3717	NY
W	8/18/2005	12/9/2005	US	C03,L92,M94,I	34	34	2767	FL
W	8/24/2005	11/8/2005	US	A96,C03,G04,I	44	44	3283	CA
W	10/7/2004	12/23/2004	US	C03,L92,M94,I	44	32	2118	LA
W	11/4/2004	4/13/2005	US	C03,L92,M94,I	34			
W	12/7/2004	5/17/2005	US	C03,J01,L92,M	44	32	3620	TX
W	1/12/2005	4/17/2005	US	C03,J01,L92,M	36	36	2951	VA
W	11/15/2004	6/18/2005	US	C03,F01,L92	44	44	071A	CA
W	12/17/2004	3/7/2005	US	C03,L92,M94,I	34	34	3755	FL
W	12/17/2004	4/9/2005	US	C03,L92,M94,I	44	32	3676	TX
W	2/19/2005	4/16/2005	US	C03,F01,L92,M	44	24	2888	IL
W	4/8/2005	5/25/2005	US	C03,L92,M94,I	44			
W	11/23/2004	3/7/2005	US	C03,L92,M94,I	44	32	3676	TX
W	11/23/2004	3/7/2005	US	C03,L92,M94,I	44	32	3676	TX

W	2/21/2005	4/13/2005 US	C03,L92,M94,F	44	32	3586	TX
W	2/21/2005	4/13/2005 US	C03,L92,M94,F	44	32	3586	TX
W	3/30/2005	7/15/2005 US	A96,C03,G04,I	44	44	3397	CA
W	5/21/2005	7/30/2005 US	C03,G04,L92,M	44	32	3676	TX
W	7/25/2005	1/14/2006 US	C03,L92,M94,M	44	32	2304	TX
W	4/7/2005	5/30/2005 US	C03,F01,L92,M	34	34	3492	AL
W	2/19/2005	8/31/2005 US	C03,G04,L92,M	44	48	3819	CA
W	9/2/2004	2/27/2005 US	C03,J01,L92,M	44			
W	4/19/2005	7/21/2005 US	A96,C03,G04,I	34	34	3304	FL
W	4/27/2005	7/8/2005 US	C03,H97,L92,M	44	48	3819	CA
W	4/27/2005	8/1/2005 US	C03,F01,L92,M	44	24	3438	WI
W	6/20/2005	8/18/2005 US	C03,F01,L92,M	34	34	19051	FL
W	6/20/2005	8/18/2005 US	C03,F01,L92,M	34	34	19051	FL
W	9/24/2004	2/6/2005 US	C03,L92	44	48	2785	CA
W	9/24/2004	2/6/2005 US	C03,L92	44	48	2785	CA
W	12/13/2004	3/23/2005 US	C03,G04,L92,M	44	32	2190	TX
W	8/22/2005	10/28/2005 US	C03,G04,L92,M	34	34	2629	FL
W	1/13/2005	4/30/2005 US	C03,L92,M94,M	34	34	2363	FL
W	1/19/2005	4/15/2005 US	C03,L92,M94,M	26	26	2157	NY

W	5/13/2005	7/23/2005 US	C03,L92,M94,I	34	34	2831	FL
W	12/22/2004	3/12/2005 US	C03,L92,M94,I	26	26	1889	NY
W	12/22/2004	3/12/2005 US	C03,L92,M94,I	26	26	1889	NY
W	12/22/2004	3/12/2005 US	C03,L92,M94,I	26	26	1889	NY
W	9/2/2005	10/28/2005 US	A97,C03,G04,I	26	26	3556	NY
W	10/8/2004	5/6/2005 US	C03,L92,X04	34	34	3808	GA
W	11/15/2004	5/20/2005 US	C03,L92,M94,I	26	26	2971	PA
W	11/15/2004	5/20/2005 US	C03,L92,M94,I	26	26	2971	PA
W	1/13/2005	4/6/2005 US	C03,L92	44	48	3448	CA
W	4/9/2005	6/11/2005 US	C03,L92,M94,I	26	26	2976	NY
W	10/1/2004	4/18/2005 US	C03,J01,L92,M	26	26	07130	NY
W	11/2/2004	1/3/2005 US	B97,C03,G04,I	26	26	3811	NY
W	11/26/2004	2/4/2005 US	B97,C03,G04,I	26	26	3403	NY
W	12/1/2004	7/18/2005 US	C03,J01,L92,M	26	26	1898	NJ
W	1/13/2005	3/18/2005 US	C03,G04,H97,I	44	24	3199	MN

W	1/13/2005	3/18/2005	US	C03,G04,H97,I	44	24	3199	MN
W	11/11/2004	3/18/2005	US	C03,M94	36	36	09064	PA
W	11/12/2004	4/26/2005	US	C03,J01,L92,N	26	26	06038	CT
W	11/12/2004	4/26/2005	US	C03,J01,L92,N	26	26	06038	CT
W	12/14/2004	2/7/2005	US	C03,L92	26	26	2323	NJ
W	1/24/2005	3/28/2005	US	A97,C03,G04,I	26	26	07126	NY
W	3/30/2005	6/23/2005	US	C03,G04,L92,N	26	26	3736	NY
W	9/24/2004	11/23/2004	CA					
W	10/26/2004	12/24/2004	US	C03,G04,H97,I	26	26	07138	NY
W	10/26/2004	12/24/2004	US	C03,G04,H97,I	26	26	07138	NY
W	10/26/2004	12/24/2004	US	C03,G04,H97,I	26	26	07138	NY
W	1/11/2005	4/24/2005	US	C03,L92,M94	44	48	563	OR
W	1/22/2005	3/4/2005	US	C03,G04,L92,N	44	24	3229	IL
W	9/16/2004	1/31/2005	CA					
W	9/29/2004	2/3/2005	US	C03,L92,M94,N	26	26	3458	PA
W	10/6/2004	11/30/2004	CA					
W	10/29/2004	1/4/2005	US	C03,L92,Z99	44	48	3504	CA
W	11/2/2004	1/10/2005	US	C03,F01,L92,N	26	26	3212	NJ
W	12/13/2004	5/31/2005	US	C03,F01,L92,N	26	26	2620	CT
W	12/13/2004	2/24/2005	CA					
W	1/12/2005	7/18/2005	US	A97,C03,G04,I	26	26	2148	CT
W	2/15/2005	7/15/2005	US	C03,G04,L92,N	44	44	3384	AZ
W	2/16/2005	4/8/2005	CA					
W	9/24/2004	12/31/2004	US	C03,J01,L92,N	26	26	2157	NY

W	10/5/2004	2/12/2005	US	C03,G04,L92,N	44	24	3848	WI
W	10/5/2004	2/12/2005	US	C03,G04,L92,N	44	24	3848	WI
W	12/1/2004	8/1/2005	US	B97,C03,G04,L	26			
W	12/1/2004	8/1/2005	US	B97,C03,G04,L	26	26	3033	CT
W	12/22/2004	5/7/2005	US	C03,G04,L92,N	26	26	07130	NY
W	12/25/2004	3/19/2005	US	C03,L92,M94,N	26	26	3207	NY
W	12/25/2004	3/19/2005	US	C03,L92,M94,N	26	26	3207	NY
W	2/7/2005	5/2/2005	US	C03,M94,N93	44	24	3345	IL
W	2/7/2005	5/2/2005	US	C03,M94,N93	44	24	3345	IL
W	5/11/2005	6/30/2005	US	C03,L92,M94,N	26	26	3403	NY
W	11/10/2004	1/27/2005	US		44			
W	11/19/2004	1/28/2005	US	B97,C03,G04,L	26	26	3958	NY
W	1/13/2005	3/14/2005	US	A97,C03,G04,L	26	26	1889	NY
W	9/24/2004	12/29/2004	US	C03,G04,L92,N	36	36	3952	PA
W	10/13/2004	11/25/2004	CA					
W	11/16/2004	1/24/2005	US	B97,C03,G04,L	26	26	07167	NY
W	12/15/2004	2/8/2005	CA					
W	1/14/2005	3/9/2005	US	C03,G04,L92,N	26	26	3403	NY
W	1/14/2005	5/9/2005	CA					
W	4/14/2005	6/30/2005	CA					
W	4/16/2005	8/31/2005	CA					

W	9/20/2004	11/23/2004 US	C03,L92,M94,I 26	24	3690	MN
W	10/1/2004	3/11/2005 US	C03,G04,T01,\ 44	48	3979	CA
W	10/6/2004	12/10/2004 US	A96,C03,G04,I 26	26	2148	CT
W	10/27/2004	1/3/2005 CA				
W	11/3/2004	3/11/2005 US	C03,L92,M94 36			
W	12/21/2004	6/30/2005 US	C03,J01,L92,N 26	26	3214	NY
W	12/21/2004	6/30/2005 US	C03,J01,L92,N 26	26	3214	NY
W	1/19/2005	4/22/2005 US	C03,G04,L92,N 26	26	3109	NY
W	2/25/2005	5/16/2005 US	C03,G04,L92,N 26	26	3033	CT
W	**4/19/2005**	**6/20/2005 US**	**C03,F01,L92,N 26**	**26**	**04029**	**MA**
W	6/20/2005	10/8/2005 US	C03,G04,L92,N 36	36	3961	PA
W	11/4/2004	1/1/2005 CA				
W	11/4/2004	12/30/2004 US	C03,G04,L92,N 44			
W	11/11/2004	1/5/2005 US	C03,L92,Z99 34			
W	11/11/2004	1/5/2005 US	C03,L92,Z99 34			
W	11/12/2004	2/7/2005 US	C03,L92 36			
W	11/23/2004	1/21/2005 US	B97,C03,G04,I 26	26	3136	NJ
W	12/1/2004	1/31/2005 US	C03,L92,M94,I 26	26	2691	NY
W	5/25/2005	9/24/2005 CA				

W	8/1/2005	10/26/2005	US	C03,G04,L92,M	26	26	3556	NY

Num-Ctrl	Code-Class	Code-ClmStat	St-SvcDlr	Code-SvcDlr	Date-RO	Num-RO	Mileage	Code-CS
1901	0	2	NY	5036	4/25/2006	3033131	25,393	ZE
1902	2	7	NY	5036	4/25/2006	3033131	25,393	ZE
1901	0	2	FL	3509	6/19/2006	50564A	14,936	ZA
1901	0	2	CA	3774	6/21/2006	1074671	4,639	ZL
1903	0	2	LA	2118	12/20/2005	3652291	22,553	ZE
1901	0	2	MO	1964	1/26/2006	1476171	18,094	ZE
1901	0	2	TX	3620	2/9/2006	390116A	17,128	ZE
1901	0	2	VA	2951	1/16/2006	2046751	9,538	ZL
1901	0	2	CA	071A	1/3/2006	573331	14,643	ZE
1901	0	2	FL	3755	5/26/2006	44874A	36,167	ZE
1902	0	2	TX	3676	6/9/2006	1354591	15,221	ZE
1902	0	2	IL	2888	6/14/2006	45177A	14,905	ZJ
1903	0	2	CA	3387	12/2/2005	385492B	5,433	ZE
1901	0	2	TX	3620	5/31/2006	396148B	23,581	ZE
2201	2	2	TX	3620	5/31/2006	396148B	23,581	ZE

1902	0	2	TX	3586	5/30/2006	270402B	26,097 ZE
2201	2	2	TX	3586	5/30/2006	270402B	26,097 ZE
1901	0	2	CA	3397	6/1/2006	08248401	9,887 ZL
1904	0	2	TX	3939	11/26/2005	123709B	7,611 ZK
1902	0	2	TX	2304	4/18/2006	342279B	4,031 ZE
1901	0	2	AL	3492	4/27/2006	2847131	29,706 ZE
1901	0	2	CA	3819	2/3/2006	870801	10,070 ZJ
1902	0	2	CA	3683	10/26/2005	2389811	7,803 ZE
1904	0	2	FL	3022	3/2/2006	4659455	7,303 ZL
1902	0	2	CA	3819	6/8/2006	958221	15,714 ZE
1901	0	2	WI	3438	2/28/2006	19184A	14,939 ZE
1902	0	2	FL	19029	5/16/2006	2121651	14,173 ZE
1903	2	7	FL	19029	5/16/2006	2121651	14,173 ZE
1901	0	2	CA	2261	5/4/2006	519676A	20,108 ZJ
1902	2	7	CA	2261	5/4/2006	519676A	20,108 ZJ
1901	0	2	TX	3437	5/9/2006	196583C	18,633 ZE
1901	0	2	FL	2629	3/24/2006	1206651	7,053 ZK
1901	0	2	FL	2363	2/20/2006	227601A	12,426 ZE
1904	0	2	NY	2157	6/7/2006	3414721	14,716 ZE

1901	0	2	FL	2831	6/19/2006 5229351	18,047	ZJ
1905	0	2	NY	1889	3/20/2006 4371511	23,471	ZH
1906	2	7	NY	1889	3/20/2006 4371511	23,471	ZH
2202	2	2	NY	1889	3/20/2006 4371511	23,471	ZH
1901	0	2	NY	3556	5/23/2006 193161	8,659	ZE
1901	0	2	GA	3808	2/24/2006 987411	11,214	ZJ
1902	0	2	PA	2971	5/16/2006 2552601	9,738	ZJ
2201	2	2	PA	2971	5/16/2006 2552601	9,738	ZJ
1902	0	2	CA	3788	3/16/2006 3470381	15,681	ZA
1901	0	2	NY	2976	6/2/2006 2644113	9,057	ZE
1901	0	2	NY	2157	5/4/2006 3392391	19,267	ZL
1902	0	2	NY	3811	2/23/2006 1477601	19,096	ZE
1903	0	2	NY	3403	5/3/2006 203433A	22,558	ZE
1901	0	2	NJ	1898	4/25/2006 356755A	32,930	ZA
1902	0	2	MN	3199	5/8/2006 4719671	14,470	ZE

1903	2	7	MN	3199	5/8/2006 4719671	14,470	ZE
1901	0	2	PA	09064	4/11/2006 173144A	33,004	ZJ
1901	0	2	CT	3422	3/9/2006 160927A	8,524	ZE
1902	2	7	CT	3422	3/9/2006 160927A	8,524	ZE
1901	0	2	IL	3229	5/4/2006 108582A	16,069	ZE
1901	0	2	NY	07094	6/6/2006 131777A	18,002	ZE
1901	0	2	NY	3109	3/27/2006 649792	4,428	ZE
1907	0	2	QC	51193	2/22/2006 44449A	50,900	ZJ
1902	0	2	NY	07138	2/24/2006 295808B	29,628	ZE
1903	2	7	NY	07138	2/24/2006 295808B	29,628	ZE
2201	2	2	NY	07138	2/24/2006 295808B	29,628	ZE
1901	0	2	OR	563	5/11/2006 15866A	11,311	ZJ
1905	0	2	IL	3229	3/3/2006 102335A	20,134	ZJ
1905	0	2	QC	54232	12/6/2005 84709D	24,315	ZL
1902	0	2	PA	2428	5/10/2006 148273A	27,090	ZE
1901	0	2	QC	53010	3/9/2006 154134A	57,304	ZL
1901	0	2	CA	3979	3/22/2006 12332A	35,765	ZE
1901	0	2	NJ	3212	3/7/2006 146722A	35,001	ZJ
1903	0	2	NY	07167	6/6/2006 5604752	26,563	ZE
1903	0	2	BC	01072	6/16/2006 134454C	56,081	ZE
1901	0	2	CT	2148	3/8/2006 3029383	9,080	ZE
1902	0	2	AZ	3384	9/13/2005 323197A	7,950	ZE
1901	0	2	ON	44176	12/19/2005 179326C	8,492	ZE
1901	0	2	NY	2157	4/19/2006 3381071	31,852	ZE

1905	0	2	WI	3848	1/19/2006 2476931	14,566	ZE
1906	2	7	WI	3848	1/19/2006 2476931	14,566	ZE
1901	0	2	CT	3033	11/28/2005 1200661	9,094	ZJ
1906	3	2	CT	3033	4/10/2006 1262861	17,880	ZE
1903	0	2	NY	2976	5/18/2006 2634901	10,568	ZE
1901	0	2	NY	3207	12/12/2005 810581	15,025	ZJ
1902	2	7	NY	3207	12/12/2005 810581	15,025	ZJ
1902	0	2	IL	3345	2/6/2006 3217131	9,936	ZE
2201	2	2	IL	3345	2/6/2006 3217131	9,936	ZE
1901	0	2	NY	3403	3/24/2006 201259A	10,267	ZE
1903	0	2	IL	38031	9/7/2005 804431	8,217	ZE
1901	0	2	NY	3958	12/2/2005 0837923	10,052	ZH
1903	0	2	NY	1889	5/18/2006 4418481	32,402	ZE
1902	0	2	PA	3952	6/15/2006 19496A	35,684	ZN
1903	0	2	QC	54238	6/8/2006 53826C	15,171	ZE
1903	0	2	NY	07167	1/23/2006 3811653	16,852	ZE
1902	0	2	QC	54237	3/22/2006 58058A	29,009	ZE
1902	0	2	NY	3403	3/15/2006 200835A	16,648	ZE
1903	0	2	SK	21049	5/29/2006 321366A	37,879	ZE
1902	0	2	QC	54196	12/8/2005 168589A	8,333	ZE
1901	0	2	QC	52235	3/2/2006 91676A	13,134	ZE

1901	0	2	NY	3273	3/27/2006	3671001	21,085 ZE
1901	0	2	CA	3979	4/7/2006	12819A	27,602 ZJ
1903	0	2	CT	2148	5/18/2005	2837452	10,757 ZL
1904	0	2	QC	52164	4/18/2006	203311C	34,205 ZE
1901	0	2	MD	3799	12/29/2005	6627851	18,476 ZE
1902	0	2	NY	3214	2/13/2006	146771A	9,750 ZE
1903	2	7	NY	3214	2/13/2006	146771A	9,750 ZE
1901	0	2	NY	3109	6/22/2006	672761	27,623 ZE
1902	0	2	CT	3033	2/21/2006	1239741	17,892 ZE
1901	0	2	MA	04029	6/2/2006	2903861	22,407 ZE
1901	0	2	PA	3961	3/14/2006	6231501	12,315 ZE
1904	0	2	MB	31061	5/11/2006	59659C	51,929 ZJ
1903	0	2	IN	2655	1/25/2006	4301211	20,772 ZE
1903	0	2	TN	2855	11/3/2005	1276341	29,123 ZE
1904	3	2	GA	17038	12/29/2005	4388801	31,863 ZH
1901	0	2	FL	19074	2/8/2006	189828A	34,081 ZE
1901	0	2	NJ	3136	4/3/2006	3289101	32,681 ZE
1901	0	2	NY	1889	5/3/2006	4408041	28,384 ZE
1902	0	2	SK	22052	3/20/2006	106267C	31,933 ZE

1901	0	2	NY	3811	.5/25/2006	1551231	20,462 ZE

Code-CT	Code-Comp	Comm-Cust
32	BF	CUSTOMER STATES THE SEAT MOVES SIDE TO SIDE PART ON ORDER:
32	BF	CUSTOMER STATES THE SEAT MOVES SIDE TO SIDE PART ON ORDER:
05	BF	DRIVERS SEAT LEANS TO THE LEFT, CUSTOMER STATES, SOP HERE. SEE RO 50154 TECH 45.
32	BF	CLIENT STATES SQUEEK FROM DRIVERS SEAT BOTTOM PART IN STOCK PER PREVIOUS DIAGNOSIS:
01	BF	CUST STATES DR SEAT VERY LOOSE:
03	BF	CUSTOMER REPORTS THE DRIVERS SEAT IS LOOSE PREVIOUS INSPECTION FOUND THE SEAT BOTTOM TO HAVE A STRESS:
01	BF	MAINT,TRIM,DRIVE , CUSTOMER STATES DRIVERS SEAT WILL NOT ADJUST UP OR DOWN ,
46	BF	CUSTOMER STATES THAT DRIVERS SIDE SEAT MOVES INSTALL SPECIAL ORDERED PARTS:
01	BF	CUSTOMER STATES DRIVER SEAT WILL NOT ADJUST STUCK WILL NOT MOVE UP OR DOWN INSTALL SPECAIL ORDER:
01	BF	CUST STATES DRIVERS SEAT IS LOOSE AND SHIFTS
32	BF	CUSTOMER REPORTS THE LEFT FRONT SEAT TILTS TO THE LEFT WHILE ADJUSTING IN UP POSITION S O PART:
41	BF	SEAT TRACK PART IN
32	BF	C,S THAT DRIVER' SIDE LUMBAR INOP
42	BF	CUSTOMER STATES DRIVER SEAT LOOSE
42	BF	CUSTOMER STATES DRIVER SEAT LOOSE

42	BF	CUST STATES DRIVER SIDE SEAT LOOSE
42	BF	CUST STATES DRIVER SIDE SEAT LOOSE
26	BF	CUSTOMER STATES THE LEFT FRONT SEAT SQUEEKS WHILE DRIVING SOP IN
32	BF	INSTALL SOP-ADJUSTER
32	BF	LEFT FRONT SEAT SEEMS TO ROCK FOREWARD & BACKWARDS INSTALL SOP
01	BF	CUSTOMER STATES DR SEAT LOOSE SOP:
01	BF	CUSTOMER STATES THAT DRIVERS FRONT SEAT IS LOOSE SOP IN STOCK:
01	BF	CHECK AND ADVISE CUST STATES DRIVER SIDE SEAT BOTTOM PANEL LOOSE:
46	BF	CUSTOMER STATES DRIVERS SEAT CLUNKS WHEN DRIVING AND WEIGHT
01	BF	CUST STATES THAT THERE IS A LOT OF LATERAL MOVEMENT ON THE DRIVER FRONT SEAT PLEASE CHECK AND ADVISE SOP IN STOCK:
32	BF	CHECK BACK SEAT PROTION OF DRIVERS SEAT BROKEN AND ADVISE
01	BF	C S THE DRIVERS SEAT SEEMS OUT OF PLACE WOBBLES:
01	BF	C S THE DRIVERS SEAT SEEMS OUT OF PLACE WOBBLES:
01	BF	CUST STATES DR SEAT MOVES A LOT .
01	BF	CUST STATES DR SEAT MOVES A LOT .
32	BF	CUSTOMER STATES FRONT PASSENGER SEAT RATTLES
42	BF	CUSTOMER STATES THE DRIVER SEAT ROCKS BACK AND FORTH S O P IN:
01	BF	CUTOMER STATES THAT THE DRIVERS SIDE SEAT SEEMS TO BE BROKEN FROM FRAME
32	BF	CUSTOMER STATES THAT THE DRIVER S SEAT IS LOOSE INSTALL S O P SEAT TRACK:

42	BF	CUSTOMER STATES DRIVER SIDE SEAT LEANS TO THE LEFT AND WOBBLES WHEN OCCUPIED DRIVING
01	BF	CUSTOMER STATES THAT DRIVERS FRONT SEAT MOVES SEEMS LOSE CK AND REPORT
01	BF	CUSTOMER STATES THAT DRIVERS FRONT SEAT MOVES SEEMS LOSE CK AND REPORT
01	BF	CUSTOMER STATES THAT DRIVERS FRONT SEAT MOVES SEEMS LOSE CK AND REPORT
32	BF	CUST STATES LEFT FRONT SEAT KEEPS SHAKING ROCKING:
42	BF	CUSTOMER STATES DRIVERS FRONT SEAT HAS EXCESSIVE MOVEMENT UPON BRAKING INSTALL ORDERED PARTS:
01	BF	CUSTOMER STATES THE ONE MOUNT FOR L F SEAT HAS COME OFF:
01	BF	CUSTOMER STATES THE ONE MOUNT FOR L F SEAT HAS COME OFF:
03	BF	CHECK L FRT SEAT SQUATS WHEN SAT ON INSTALL S O PARTS SEAT F FRAME ASSY:
02	BF	CUST SAYS DRIVERS SEAT MOVES AND FEELS LOOSE SEAT BOTTOM:
01	BF	CUSTOMER REQUEST WE INSTALL PART ON HOLD FOR DRIVER SIDE FRONT SEAT REPAIR:
32	BF	CUST SAYS L S FRT SEAT LEANING TOWARDS R SIDE:
32	BF	CUST STATED TO CHECK THE SEAT WHICH WAS NOT OPERATING..
01	BF	SOP--CUSTOMER STATES DRIVERS SEAT FRAME IS BROKEN AND IT ROCKS BACK AND FORTH . INSTALL SOP.
32	BF	CUSTOMER STATES THE DRIVERS SEAT IS LOOSE SOP HERE:

32	BF	CUSTOMER STATES THE DRIVERS SEAT IS LOOSE SOP HERE:
01	BF	C,S THAT THE D,S FRONT SEAT SEEMS TO BE ROCKING WHILE DRIVING..PARTS IN STOCK
01	BF	CUSTOMER STATES DRIVER SEAT TRACK BROKEN
01	BF	CUSTOMER STATES DRIVER SEAT TRACK BROKEN
27	BF	C,S DRIVERS SIDE SEAT IS UNEVEN
01	BF	CUST STATES DRIVER SIDE SEAT BASE IS LOOSE AS S,O,PART
23	BF	CUSTOMER STATES LEFT FRONT SEAT INOP WILL NOT MOVE:
01	BF	
32	BF	CUSTOMER STATES THE DRIVER SIDE SEAT SHIFTS WHILE DRIVING AT NORMAL SPEEDS
32	BF	CUSTOMER STATES THE DRIVER SIDE SEAT SHIFTS WHILE DRIVING AT NORMAL SPEEDS
32	BF	CUSTOMER STATES THE DRIVER SIDE SEAT SHIFTS WHILE DRIVING AT NORMAL SPEEDS
42	BF	C ST DRVR SEAT VERY LOOSE
27	BF	C,S DRIVERS SEAT IS LOOSE INSTALL SOP
21	BF	
01	BF	INSTALL ORDERED SEAT BOTTOM FRAME ASSY
46	BF	
01	BF	CUSTOMER STATES THERE IS A FRONT SEAT MOTOR LOOSE UNDER THE FRONT SEAT CHECK AND ADVISE
01	BF	C,S DRIVER FRONT SEAT LOOSE INSTALL SOP
01	BF	C SDRIVER SIDE SEAT INOP -- SOP PARTS HERE
41	BF	
01	BF	CUSTOMER STATES THE DRIVERS SIDE FRONT SEAT IS LOOSE:
32	BF	C,S THE RIGHT SEAT DOES NOT MOVE- INSTALL SOP
32	BF	
32	BF	CUST STATES D S SEAT IS BROKEN:

01	BF	CUST STATES DRIV SEAT ROCKS:
01	BF	CUST STATES DRIV SEAT ROCKS:
01	BF	CUSTOMER STATES DRIVERS SEAT IS LOOSE PART ORDERED NOW IN:
01	BF	CUSTOMER STATES SEAT MOVES AROUND FRAME ORDERED NOW IN:
32	BF	CUSTOMER STATES WHEN L F SEAT IS IN UP POSITION LOWER SECTION SEAT ROCKS:
01	BF	CUSTOMER STATES THE DRIVERS SEAT IS CROOKED:
01	BF	CUSTOMER STATES THE DRIVERS SEAT IS CROOKED:
32	BF	C STATES DRIVER SEAT IS LOOSE:
32	BF	C STATES DRIVER SEAT IS LOOSE:
32	BF	CUST STATED TO CHECK THE SEAT NOT MOVING.
32	BF	RF SEAT VIB WHILE CAR IS DRIVEN AT ANY SPEED:
03	BF	FRT SEAT BROKEN FELL TO LEFT
32	BF	CUSTOMER REQUEST DRIVERS SEAT IS BROKEN CUST STATES INSTALL SOP SEAT ADJUSTER RO 441213 59
01	BF	CUSTOMER STATES DRIVER'S SEAT SEEMS LOOSE (SOP)
42	BF	
01	BF	C S NOISE IN D-SEAT -PARTS ARE HERE -SEAT MOVES AND NOT STRA
32	BF	
32	BF	CUST STATED TO CHECK THE SEAT WHICH WAS NOT MOVING.
01	BF	
32	BF	
01	BF	

32	BF	CUST STATES POWER SEAT INOP
42	BF	CUSTOMER STATES DRIVERS SEAT BOTTOM VERY LOOSE
42	BF	CUSTOMER STATES HEARS A RATTLE FROM PASSENGER SEAT WHILE DRIVING :
32	BF	
42	BF	CUSTOMER STATES DRIVERS SEAT DOES NOT SEEM TO BE BOLTED DOWN
01	BF	CUSTOMER STATES THE DRIVERS SEAT IS FALLING OVER, HAS IT JACKED UP SO HE CAN DRIVE IN
01	BF	CUSTOMER STATES THE DRIVERS SEAT IS FALLING OVER, HAS IT JACKED UP SO HE CAN DRIVE IN
32	BF	CUSTOMER STATES LEFT FRONT SEAT INOP SOP INSTOCK:
01	BF	CUSTOMER STATES CHECK DREVERS SEAT WON T MOVE:
01	BF	CUSTOMER STATES THE DRIVERS SEAT FRAME WELD HAS FAILED AND THE SEAT IS COMING APART SPORD REPLACE THE SEAT FRAME:
32	BF	CUSTOMER STATES THE DRIVER'S SEAT WILL NOT GO UP AND DOWN, MAKES A LOUD POPPING NOISE
26	BF	
32	BF	REAR OF DRIVER SEAT BOTTOM WILL NOT RAISE OR LOWER CAN HEAR THE MOTOR RUN:
41	BF	
01	BF	THE DRIVERS SEAT FRAME IS BROKEN
32	BF	CUST STATES SEAT GOINT TO SIDE WHEN TRYING TO MOVE UP SOP PART
32	BF	CUSTOMER STATES THAT THERE IS A NOISE COMING FROM SEAT I INSTALL SOP:
32	BF	CUSTOMER STATES LEFT FRONT SEAT FRAME IS LOSE AND FOUND TO BE CRACKED INSTALL SEAT FRAME ASSY ORDERED ON RO 439622
32	BF	

01	BF	CUST SAYS L S FRT SEAT DOESNT MOVE UP OR DOWN:

Comm-Tech	Claim$	LaborHrs	Labor$	Part$	Date-CSR
CONFIRM CUSTOMER CONCER AND FOUND SEAT BOTTOM IS CRACKED CAUSING SEAT ROCKS SIDE TO SIDE INSTALL NEW SEAT BOTTOM WITH MO	$ 650.34	1.30	$ 110.50	$ 539.84	5/31/2006
CONFIRM CUSTOMER CONCER AND FOUND SEAT BOTTOM IS CRACKED CAUSING SEAT ROCKS SIDE TO SIDE INSTALL NEW SEAT BOTTOM WITH MO	$ 35.00	.00	$ -	$ 35.00	5/31/2006
14936 REPLACE LT FT POWER SEAT ADJUSTER (SLIDE ASSY,) LT REAR ACTUATOR STRIPPED OUT SEAT GOES UP CROOKED LEANS TO	$ 598.10	1.30	$ 94.25	$ 503.85	6/30/2006
STRESS TYPE CREAK NOISE WHEN FRAME IS FULLY EXTENDED FAILURE OF SEAT FRAME UNIT IMPROPER WELD LOCATION REPLACED DRIVE	$ 614.63	1.30	$ -	$ 505.43	6/30/2006
FOUND CROSSBAR ON LEFT SEAT ADJUSTER BROKEN REPLACED LEFT FRONT SEAT ADJUSTER AND CHECKED OKAY:	$ 588.35	1.30	$ 84.50	$ 503.85	12/31/2005
STRESS FRACTURE REPLACED LEFT SEAT FRAME AND SLIDE ASSEMBLY DI 7 OF AN HOUR DUE TO OVERLAP:	$ 946.55	2.40	$ -	$ 771.45	1/31/2006
17130 156 WARRANTY CHECK & INSPECT DRIVER SEAT LOOSE & WONT ADJUST. FOUND SEAT ADJUSTER FRAME COME APART. REPLACE	$ 672.51	1.30	$ 110.18	$ 562.33	3/31/2006
SEAT FRAME BROKEN AT WELD DIAGNOSE AND REPLACE LEFT SIDE SEAT FRAME AND RECHECK:	$ 611.10	1.30	$ 107.25	$ 503.85	1/31/2006
BROKEN MOTOR REPLACED DRIVER SEAT ADJUSTER:	$ 587.70	1.30	$ 83.85	$ 503.85	1/31/2006
36167 VERIFIED COMPLAINT LAST VISIT. VEHICLE HAS BROKEN LIFT ARM REPLACED ASSY AS NEEDED. ALL OK AT THIS TIME	$ 594.85	1.30	$ 91.00	$ 503.85	6/30/2006
INTERNAL FAILURE REPLACE DRIVERS FRONT SEAT ADJUSTER:	$ 676.41	1.30	$ 114.08	$ 562.33	6/30/2006
14905 CHECK L,F SEAT INOP FOUND L,F SEAT TRACK CRACKED REPLACED L,F SEAT TRACK AND RETESTED	$ 637.10	1.30	$ 133.25	$ 503.85	6/30/2006
REPLACED SEATBCK FRAME TO RESOLVE	$ 609.15	1.30	$ 105.30	$ 503.85	12/31/2005
23581 REPLACED DIVERS FRONT SEAT FRAME DUE TO FRAME CAME APART AT WELDS IN 2 PLACES WARRANTY	$ 708.50	1.30	$ 110.18	$ 598.32	6/30/2006
23581 REPLACED DIVERS FRONT SEAT FRAME DUE TO FRAME CAME APART AT WELDS IN 2 PLACES WARRANTY	$ 35.00	.00	$ -	$ 35.00	6/30/2006

26097 SEAT FRAME,RAIL BROKEN REMOVED SEAT INSTALLED SEAT FRAME, RAILS OK	$ 654.31	1.30	$ 91.98	$ 562.33	6/30/2006
26097 SEAT FRAME,RAIL BROKEN REMOVED SEAT INSTALLED SEAT FRAME, RAILS OK	$ 35.00	.00	$ -	$ 35.00	6/30/2006
LOOSE WORN SEAT TRACK NECC TO REPLACE SEAT TRACK	$ 616.27	1.30	$ 110.84	$ 505.43	6/30/2006
7611 D,SEAT CREAKS AND ROCKS REPLACED DRIVERS SEAT ADJUSTER PART NUMBER 87450- CA66A	$ 669.39	1.30	$ 105.30	$ 564.09	12/31/2005
4031 CUST STATES LEFT FRONT SEAT ROCKS FORWARD AND BACKWARD VERIFIED CUSTOMER CONCENR AND FOUNDLEFT FRONT SEAT RAIL	$ 715.32	1.30	$ 117.00	$ 598.32	4/30/2006
SEATY FRAM CRACKED OFF DUE TO POOR WELD R R SEAT RAIL INCLUDING LOWER CUSION LOWER SHROUD AND WIRING HARNES:	$ 600.05	1.30	$ 96.20	$ 503.85	4/30/2006
FOUND WELDS ON THE MAIN SUPPORT BARS ON THE LOWER SEAT FRAME REMOVED SEAT AND INSTALLED NEW LOWER SEAT FRAME RECHECKED	$ 693.06	1.90	$ 187.63	$ 505.43	2/28/2006
TECH VERIFIED SEAT PANEL LOOSE TECH REMOVED AND REINSTALL SEAT PANEL:	$ 616.91	1.30	$ 111.48	$ 505.43	12/31/2005
NOISY ADJ ASSY BAD RPL RIGHT SEAT SLIDE ASS'Y BRACKET	$ 612.03	1.30	$ 106.60	$ 505.43	3/31/2006
UPON INSPECTION TRACED TO A BROKEN SEAT FRAME ASSEMBLY REMOVED FROM STOCK 9869 AND INSTALLED INTO CUST VEHICLE INSTALLE	$ 671.73	1.70	$ 167.88	$ 503.85	6/30/2006
14939 DRIVERS SEAT BROKEN BOTTOM RAIL ASSLY IN REAR BROKEN REPL RAIL ASSLY	$ 612.08	1.30	$ 108.23	$ 503.85	3/31/2006
FOUND SEAT ADJUSTER BRACKET BROKEN OFF REPLACED SEAT ADJUSTER ASSEMBLY:	$ 610.20	1.30	$ 106.35	$ 503.85	5/31/2006
FOUND SEAT ADJUSTER BRACKET BROKEN OFF REPLACED SEAT ADJUSTER ASSEMBLY:	$ 70.00	.00	$ -	$ 70.00	5/31/2006
FOUND FRAME BRKN RPL SEAT FRAME .	$ 659.20	1.30	$ 155.35	$ 503.85	5/31/2006
FOUND FRAME BRKN RPL SEAT FRAME .	$ 90.00	.00	$ -	$ 90.00	5/31/2006
18633 1375 CUSTOMER STATES RATTLE FROM PASS. SEAT. TEST DROVE AND RATTLE COMING FROM SEAT TRACK ASSEMBLY--R&R	$ 730.77	1.30	$ 109.20	$ 621.57	5/31/2006
INTERNAL FAILURE WITHIN SEAT FRAME ASSY REPLACED DRIVERS SEAT FRAME:	$ 599.36	1.30	$ 93.93	$ 505.43	3/31/2006
12430 SEAT TRACK IS BROKEN REPLACED SEAT TRACK ASSEMBLY AND NOW PERFORMING TO MANUFACTURE SPECS	$ 610.45	1.30	$ 106.60	$ 503.85	3/31/2006
FOUND SEAT FRAME LOOSE BECAUSE CRACKED REPLACED DRIVER S SEAT FRAME:	$ 626.05	1.30	$ 122.20	$ 503.85	6/30/2006

REPLACE LF SEAT TRACK AS NEEDED. PART #87450CA06A SEAT METAL HOLDER COMING APART.	$ 627.35	1.30	$ 123.50	$ 503.85	6/30/2006
CAR WAS CHECKED BY TECH PERFORMED DIAG FOUND LEFT FRONT SEAT FRAME CRACKED REPLACED RECHECK COMPLETED	$ 615.98	1.30	$ 112.13	$ 503.85	4/30/2006
CAR WAS CHECKED BY TECH PERFORMED DIAG FOUND LEFT FRONT SEAT FRAME CRACKED REPLACED RECHECK COMPLETED	$ 70.00	.00	$ -	$ 70.00	4/30/2006
CAR WAS CHECKED BY TECH PERFORMED DIAG FOUND LEFT FRONT SEAT FRAME CRACKED REPLACED RECHECK COMPLETED	$ 70.00	.00	$ -	$ 70.00	4/30/2006
CHECKED AND FOUND LEFT FRONT SEAT TRACK CRACKED IN FRONT SUPPORT BAR CAUSING SEAT TRACK TO SHAKE REPLACED LEFT FRONT SEA	$ 606.83	1.30	$ 101.40	$ 505.43	6/30/2006
INSTALLED NEW DRIVER SIDE SEAT ADJUSTER ASSEMBLY SEAT ADJUSTER COMING LOOSE:	$ 618.25	1.30	$ 114.40	$ 503.85	2/28/2006
TECH FOUND THE LEFT FRONT SEAT TRACK ASSEMBLEY BROKEN THE TECH REPLACED THE SEAT BOTTOM SLIDES VE46AA 1 4 ZJ 01:	$ 612.40	1.30	$ 108.55	$ 503.85	5/31/2006
TECH FOUND THE LEFT FRONT SEAT TRACK ASSEMBLEY BROKEN THE TECH REPLACED THE SEAT BOTTOM SLIDES VE46AA 1 4 ZJ 01:	$ 28.00	.00	$ -	$ 28.00	5/31/2006
FAILED ADJUSTER ASSY VERIFIED CONCERN AND PERFORMEDDIAG AND TRACED TO FAILED SEAT ADJUSTER ASSY REPLACED SEAT ADJUSTER	$ 631.25	1.30	$ 127.40	$ 503.85	4/30/2006
VERIFY CONDITION FOUND BOTTOM OF LEFT FRONT SEAT SEPARATED AT BASE REMOVE SEAT INSTALL NEW SEAT BOTTOM AND REASSEMBLE	$ 619.55	1.30	$ 115.70	$ 503.85	6/30/2006
BAR ON SEAT RAIL BROKEN R R SEAT RAIL:	$ 615.65	1.30	$ 111.80	$ 503.85	5/31/2006
CONFIRMED CUST COMPLAINT CHECK AND FOUND THE REAR TRANSVERSE BAR SNAPPED RIGHT WHERE IT IS WELDED ON TO THE REMOVED AND	$ 608.13	1.30	$ 102.70	$ 505.43	3/31/2006
FOUND THAT THE SEAT ADJUSTER WAS FAILED INTERNALLY CAUSING TTHE PROBLEM. REPLACED THE ADJUSTER TO RESOLVE THE PROBLEM.	$ 615.93	1.30	$ 110.50	$ 505.43	5/31/2006
SEAT FRAME WEND BROKE OFF	$ 712.07	1.30	$ 113.75	$ 598.32	6/30/2006
TRACED TO AND REPLACED SEAT BOTTOM:	$ 635.43	1.30	$ 130.00	$ 505.43	5/31/2006

TRACED TO AND REPLACED SEAT BOTTOM:	$ 35.00	.00	$ -	$ 35.00	5/31/2006
REPLACED LEFT FRT SEAT FRAME	$ 592.90	1.30	$ 89.05	$ 503.85	4/30/2006
8524 FOUND THAT DRIVERS FRONT SEAT WELD FOR ADJ. ASS Y WAS CRACKED REPLACED DRIVERS FRONT SEAT ADJ. SEAT ASSY. SEAT	$ 630.84	1.30	$ 91.00	$ 539.84	4/30/2006
8524 FOUND THAT DRIVERS FRONT SEAT WELD FOR ADJ. ASS Y WAS CRACKED REPLACED DRIVERS FRONT SEAT ADJ. SEAT ASSY. SEAT	$ 30.00	.00	$ -	$ 30.00	4/30/2006
16069 SEAT FRAME BOTTOM IS BENT REPLACED SEAT FRAME BOTTOM	$ 635.15	1.30	$ 131.30	$ 503.85	5/31/2006
REPLACE SEAT SLIDE ASSEMBLY LOOSE SEAT BASEFRAME CRAKED	$ 652.03	1.30	$ 110.50	$ 541.53	6/30/2006
FOUND SEAT TRACK SEIZED REPLACE LEFT FRONT SEAT ASSY:	$ 788.47	1.30	$ 114.40	$ 674.07	3/31/2006
	$ 207.97	1.30	$ 71.11	$ 136.86	3/31/2006
VERFIED COMPLAINT FOUND SEAT ROCK BACK A ND FORTH REPLACED LEFT FRONT POWER SEAT LIFT ASS'Y TO REPAIR CK OK	$ 615.93	1.30	$ 110.50	$ 505.43	3/31/2006
VERFIED COMPLAINT FOUND SEAT ROCK BACK A ND FORTH REPLACED LEFT FRONT POWER SEAT LIFT ASS'Y TO REPAIR CK OK	$ 104.95	.00	$ -	$ 104.95	3/31/2006
VERFIED COMPLAINT FOUND SEAT ROCK BACK A ND FORTH REPLACED LEFT FRONT POWER SEAT LIFT ASS'Y TO REPAIR CK OK	$ 70.00	.00	$ -	$ 70.00	3/31/2006
REPL DRT SEAT ADJUSTER	$ 603.95	1.30	$ 100.10	$ 503.85	5/31/2006
20134 FAILED LEFT FRONT SEAT BOTTON REAR MOUNT REPLACE LEFT FRONT SEAT BOTTOM	$ 636.73	1.30	$ 131.30	$ 505.43	3/31/2006
	$ 102.60	1.30	$ 102.60	$ -	2/28/2006
RPL SLIDE LIFT ASSY	$ 611.75	1.30	$ 107.90	$ 503.85	5/31/2006
	$ 220.00	1.30	$ 83.14	$ 136.86	4/30/2006
35765 CONFIRMED THAT DRIVERS SIDE SEAT MOTOR IS LAYING ON THE FLOOR. MOTOR HAS BROKEN OFF FROM THE SEAT ADJUSTER	$ 646.85	1.30	$ 143.00	$ 503.85	3/31/2006
,	$ 678.03	1.30	$ 115.70	$ 562.33	3/31/2006
FRAME BROKEN RPL ONE RECLINING DEVICE ASS'Y	$ 594.85	1.30	$ 91.00	$ 503.85	6/30/2006
	$ 788.90	1.30	$ 121.41	$ 667.49	6/30/2006
VERIFIED CUSTOMER COMPLAINT FOUND BROKEN WELD ON SEAT TRACK REMOVED AND REPLACED LEFT FRONT SEAT TRACK RECK OK:	$ 607.81	1.30	$ 102.38	$ 505.43	3/31/2006
7950 FOUND R,F SEAT NO ADJUSTING FRONT TO BACK, TESTED AND FOUND MOTOR HAVING DEAD SPOT IN IT. REPLACED R,F POWER	$ 664.00	1.30	$ 129.03	$ 534.97	9/30/2005
	$ 245.74	1.30	$ 108.88	$ 136.86	12/31/2005
TECH FOUND THE D S SEAT TRACK BROKEN AT FRAME TECH REPLACED THE D S SEAT FRAME:	$ 615.65	1.30	$ 111.80	$ 503.85	4/30/2006

SEAT FRAME IS CRACKED AND DOES NOT HOLD SEAT SECURELY REPLACED ADJUSTER ASSY:	$ 621.94	1.30	$ 116.51	$ 505.43	2/28/2006
SEAT FRAME IS CRACKED AND DOES NOT HOLD SEAT SECURELY REPLACED ADJUSTER ASSY:	$ 90.00	.00	$ -	$ 90.00	2/28/2006
CRACKED DRIVERS SEAT TRACK FRAME REMOVED DRIVERS SEAT REPALCED SEAT TRACK FRAME REINSTALLED SEAT CHECKED OK:	$ 608.13	1.30	$ 102.70	$ 505.43	12/31/2005
CONFIRMED CUSTOMERS CONPLAINT FOUND SEAT BOTTOM BRACKETS BROKEN REPLACED LOWER SEAT BOTTOM:	$ 608.13	1.30	$ 102.70	$ 505.43	4/30/2006
CRACKED AT THE WELDS ADJUSTER AND THE MOTOR REPLACED LOWER SEAT TRACK:	$ 621.13	1.30	$ 115.70	$ 505.43	6/30/2006
FOUND THE DRIVERS SEAT FRAME BROKEN REPLACE THE DRIVERS SEAT FRAME:	$ 656.19	1.30	$ 116.35	$ 539.84	12/31/2005
FOUND THE DRIVERS SEAT FRAME BROKEN REPLACE THE DRIVERS SEAT FRAME:	$ 120.00	.00	$ -	$ 120.00	12/31/2005
FOUND SEAT WELD ON FRAME REPLACE SEAT FARME:	$ 659.44	1.30	$ 119.60	$ 539.84	2/28/2006
FOUND SEAT WELD ON FRAME REPLACE SEAT FARME:	$ 35.00	.00	$ -	$ 35.00	2/28/2006
FOUND THAT THE SEAT ADJUSTER FAILED INTERNALLY CAUSING THE PROBLEM. REPLACED THE SEAT ADJUSTER TO RESOLVE THE PROBLEM.	$ 655.86	1.30	$ 110.50	$ 545.36	3/31/2006
REPL LOWER FRT SEAT FRME ASSY:	$ 290.14	1.30	$ 110.31	$ 179.83	9/30/2005
SEAST RPL LEFT SEAT CUSHION TRIM	$ 616.30	1.30	$ 112.45	$ 503.85	3/31/2006
SEAT ASSY BROKEN REPLACED SOP SEAT TRACK ASSEMBLY REAR ADJUSTER ARM BROKEN REPLACED COMPLETE ASSEMBLY AND RETESTED A	$ 617.56	1.30	$ 112.13	$ 505.43	5/31/2006
CONFIRMED ISSUE FOUND LEFT SEAT LOOSE RA TTLING AORUND FOUND SEAT TRACK FRAME IS BROKEN REMOVED AND REPLACED WITH	$ 583.43	1.30	$ 78.00	$ 505.43	6/30/2006
	$ 763.04	1.30	$ 95.55	$ 667.49	6/30/2006
BROKEN RACKET ON SEAT FRAME RPL LEFT SEAT SLIDE LIFT ASS'Y	$ 594.85	1.30	$ 91.00	$ 503.85	2/28/2006
	$ 311.53	1.30	$ 88.61	$ 222.92	5/31/2006
FOUND THAT THE SEAT LIFT ASSY WAS FAILED INTERNALLY CAUSING THE PROBLEM. REPLACED THE ASSY TO RESOLVE THE PROBLEM.	$ 615.93	1.30	$ 110.50	$ 505.43	3/31/2006
	$ 751.28	1.30	$ 83.79	$ 667.49	6/30/2006
	$ 230.98	1.30	$ 94.12	$ 136.86	12/31/2005
	$ 226.43	1.30	$ 89.57	$ 136.86	3/31/2006

TRACED TO INTERNAL FAILURE OF LIFT ASSM REPLACE	$ 606.55	1.30	$ 102.70	$ 503.85	4/30/2006
27602 INSPECT DRIVER'S SEAT FOUND THE LIFTER HAS BROKEN AT LEFT REAR SIDE OF SEAT. RECOMEND REPLACEMENT TO CORRECT	$ 682.86	1.30	$ 143.00	$ 539.86	5/31/2006
VERIFIED COMPLAINT FOUND PASSENGER SIDE SEAT BOTTOM LOOSE NECESSARY TO REPLACE SEAT BOTTOM REPLACED RIGHT FRONT SEAT BOT	$ 637.35	1.30	$ 102.38	$ 534.97	5/31/2005
	$ 225.35	1.30	$ 88.49	$ 136.86	4/30/2006
LOOSE TIGHTEN VARIOUS BOLTS TO SEAT TRACK AND FRAME ASSEMBLY	$ 39.88	.50	$ 39.88	$ -	1/31/2006
.	$ 678.80	1.30	$ 110.50	$ 568.30	2/28/2006
.	$ 135.00	.00	$ -	$ 135.00	2/28/2006
INTERNAL MFAILURE IN SEAT MOTOR REPLACE LEFT FRONT SEAT MOTOR AND SLIDE:	$ 619.83	1.30	$ 114.40	$ 505.43	6/30/2006
TRACK ASSEMBLY BROKEN REPLACED DRIVERS SEAT BOTTOM:	$ 608.13	1.30	$ 102.70	$ 505.43	3/31/2006
REMOVED THE DRIVERS SEAT AND LOWER FRAME ASSEMBLY REPLACED THE DEFECTIVE FRAME AND REINSTALLED COMPLETED:	**$ 594.85**	**1.30**	**$ 91.00**	**$ 503.85**	**6/30/2006**
FOUND INTERNAL FAILURE OF SEAT LIFT,SLIDE ASSY., REPLACED ASSY. AND CHECKED OPERATION, O.K.	$ 602.93	1.30	$ 97.50	$ 505.43	3/31/2006
	$ 231.20	1.30	$ 94.34	$ 136.86	5/31/2006
REAR RISER MOTOR HAS FALLEN OFF THE RISER REPLACED DRIVER FRONT SEAT RISER VH40AA:	$ 650.33	1.30	$ 97.50	$ 552.83	2/28/2006
	$ 608.48	1.30	$ 103.05	$ 505.43	12/31/2005
FOUND THE LOWER SEAT FRAME BROKEN INTO. REPLACED THE BROKEN FRAME	$ 598.75	1.30	$ 94.90	$ 503.85	2/28/2006
DEFECTIVE SEAT TRACK ASSY	$ 607.20	1.30	$ 103.35	$ 503.85	2/28/2006
TECH CONFIRMED NOISE FOUND SEAT TRACK STOPPED MOVING AND TWISTED COULD NOT STRAIGHTEN OUT REMOVED AND REPLACED SEAT TR	$ 677.84	1.30	$ 113.75	$ 564.09	4/30/2006
CK AND FOUND INTERNAL FAILURE IN SEAT REPLACE SEAT ADJUSTER ASSY	$ 615.98	1.30	$ 112.13	$ 503.85	5/31/2006
	$ 235.44	1.30	$ 98.58	$ 136.86	3/31/2006

INSPECTED AND FOUND SEAT ASSY BROKEN AT THE FACTORY WEILD REPLACED ADJUSTER ASSY:	$ 621.13	1.30	$ 115.70	$ 505.43	5/31/2006

Code-Op1	Desc-Code-Op1	Code-Op2	Desc-Code-Op2	Code-Op3	Desc-Code-Op3	Num-Part1	Qty-Part1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
						87450CA06A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA01A	1
VH32AA	RPL LEFT SEAT CUSHION FRAME AS:	VH40AA	RPL LEFT SE/			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y					87450CA06A	1
						87450CA06A	0

VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
				87450CA06A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH26AA	R&I LEFT FRONT SEAT ASS'Y	VH40AA	RPL LEFT SE/	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA010	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	VH9999	STRAIGHT TI\	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA01A	1
				87450CA01A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
				87450CA06A	0
VH24AA	RPL RIGHT SEAT SLIDE/LIFT ASS'Y			87400CA600	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1

VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
		87450CA06A	0
		87450CA06A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA01A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA010	1
		87450CA010	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1

				87450CA66A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
				87450CA06A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA01A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA010	0
				87450CA010	0
				87450CA010	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA610	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA01A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH24AA	RPL RIGHT SEAT SLIDE/LIFT ASS'Y			87400CA600	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	VH40AA	RPL LEFT SE/	87450CA01A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1

VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
		87450CA66A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
		87450CA06A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
		87450CA06A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH24AA	RPL RIGHT SEAT SLIDE/LIFT ASS'Y	87400CA000	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA01A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA01A	1

VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH24AA	RPL RIGHT SEAT SLIDE/LIFT ASS'Y			87400CA600	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH9999	STRAIGHT TIME			87450CA010	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
				87450CA06A	0
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	VH40AA	RPL LEFT SE/	87450CA01A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA01A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA66A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA06A	1
VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y			87450CA01A	1

VH40AA	RPL LEFT SEAT SLIDE/LIFT ASS'Y	87450CA66A	1

Desc-Part1	Num-Part2	Qty-Part2	Desc-Part2	Num-Part3	Qty-Part3	Desc-Part3	Date-SysAdd
ADJUSTER ASSY-FRONT SEAT,L	VORHK25438		1				5/3/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX		1				5/3/2006
ADJUSTER ASSY-FRONT SEAT,L							6/19/2006
ADJUSTER ASSY-FRONT SEAT,L							6/22/2006
ADJUSTER ASSY-FRONT SEAT,L							12/27/2005
ADJUSTER ASSY-FRONT SEAT,L	87351CA000		1 FRAME ASSY·				1/27/2006
ADJUSTER ASSY-FRONT SEAT,L							2/13/2006
ADJUSTER ASSY-FRONT SEAT,L							1/17/2006
ADJUSTER ASSY-FRONT SEAT,L							1/5/2006
ADJUSTER ASSY-FRONT SEAT,L							6/16/2006
ADJUSTER ASSY-FRONT SEAT,L							6/19/2006
ADJUSTER ASSY-FRONT SEAT,L							6/15/2006
ADJUSTER ASSY-FRONT SEAT,L							12/8/2005
ADJUSTER ASSY-FRONT SEAT,L	VORHKW188C		1				6/7/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX		1				6/7/2006

ADJUSTER ASSY-FRONT SEAT,L			6/12/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	6/12/2006
ADJUSTER ASSY-FRONT SEAT,L			6/6/2006
ADJUSTER ASSY-FRONT SEAT,L			11/30/2005
ADJUSTER ASSY-FRONT SEAT,L	VORHJT6412	1	4/20/2006
ADJUSTER ASSY-FRONT SEAT,L			4/28/2006
ADJUSTER ASSY-FRONT SEAT,L			2/6/2006
ADJUSTER ASSY-FRONT SEAT,L			12/6/2005
ADJUSTER ASSY-FRONT SEAT,L			3/6/2006
ADJUSTER ASSY-FRONT SEAT,L			6/15/2006
ADJUSTER ASSY-FRONT SEAT,L			3/17/2006
ADJUSTER ASSY-FRONT SEAT,L			5/22/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	5/22/2006
ADJUSTER ASSY-FRONT SEAT,L			5/12/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	5/18/2006
ADJUSTER ASSY-FRONT SEAT,RH			5/16/2006
ADJUSTER ASSY-FRONT SEAT,L			3/28/2006
ADJUSTER ASSY-FRONT SEAT,L			3/3/2006
ADJUSTER ASSY-FRONT SEAT,L			6/8/2006

ADJUSTER ASSY-FRONT SEAT,L			6/21/2006
ADJUSTER ASSY-FRONT SEAT,L			4/10/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	4/10/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	4/10/2006
ADJUSTER ASSY-FRONT SEAT,L			6/5/2006
ADJUSTER ASSY-FRONT SEAT,L			2/27/2006
ADJUSTER ASSY-FRONT SEAT,L			5/23/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	5/26/2006
ADJUSTER ASSY-FRONT SEAT,L			3/30/2006
ADJUSTER ASSY-FRONT SEAT,L			6/26/2006
ADJUSTER ASSY-FRONT SEAT,L			5/4/2006
ADJUSTER ASSY-FRONT SEAT,L			2/27/2006
ADJUSTER ASSY-FRONT SEAT,L			5/5/2006
ADJUSTER ASSY-FRONT SEAT,L	VORHK24906	1	6/2/2006
ADJUSTER ASSY-FRONT SEAT,L			5/9/2006

ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	5/9/2006
ADJUSTER ASSY-FRONT SEAT,L			4/25/2006
ADJUSTER ASSY-FRONT SEAT,L	VORHHX8639	1	3/29/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	4/4/2006
ADJUSTER ASSY-FRONT SEAT,L			5/12/2006
ADJUSTER ASSY-FRONT SEAT,L	VORHM14564	1	6/15/2006
ADJUSTER ASSY-FRONT SEAT,L	87451CA600	1 DEVICE - REC	3/28/2006
ADJUSTER ASSY-FRONT SEAT,L			2/23/2006
ADJUSTER ASSY-FRONT SEAT,L	87450CA66A	1 ADJUSTER AS	3/2/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	3/2/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1	3/2/2006
ADJUSTER ASSY-FRONT SEAT,L			5/19/2006
ADJUSTER ASSY-FRONT SEAT,L			3/15/2006
ADJUSTER ASSY-FRONT SEAT,L			12/27/2005
ADJUSTER ASSY-FRONT SEAT,L			5/10/2006
ADJUSTER ASSY-FRONT SEAT,L			4/7/2006
ADJUSTER ASSY-FRONT SEAT,L			3/30/2006
ADJUSTER ASSY-FRONT SEAT,L			3/13/2006
ADJUSTER ASSY-FRONT SEAT,L			6/20/2006
ADJUSTER ASSY-FRONT SEAT,L			6/21/2006
ADJUSTER ASSY-FRONT SEAT,L			3/10/2006
ADJUSTER ASSY-FRONT SEAT,RH			9/19/2005
ADJUSTER ASSY-FRONT SEAT,L			12/30/2005
ADJUSTER ASSY-FRONT SEAT,L			4/20/2006

ADJUSTER ASSY-FRONT SEAT,L					1/24/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1			1/24/2006
ADJUSTER ASSY-FRONT SEAT,L					11/29/2005
ADJUSTER ASSY-FRONT SEAT,L					4/11/2006
ADJUSTER ASSY-FRONT SEAT,L					6/13/2006
ADJUSTER ASSY-FRONT SEAT,L	VORHFR2503	1			12/19/2005
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1			12/19/2005
ADJUSTER ASSY-FRONT SEAT,L	VORHH31593	1			2/8/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1			2/8/2006
ADJUSTER ASSY-FRONT SEAT,L	87380CA001	1	FINISHER AS	87558CA001	1 COVER-SEAT 3/27/2006
ADJUSTER ASSY-FRONT SEAT,RH					9/8/2005
ADJUSTER ASSY-FRONT SEAT,L					2/3/2006
ADJUSTER ASSY-FRONT SEAT,L					5/19/2006
ADJUSTER ASSY-FRONT SEAT,L					6/15/2006
ADJUSTER ASSY-FRONT SEAT,L					6/8/2006
ADJUSTER ASSY-FRONT SEAT,L					2/17/2006
ADJUSTER ASSY-FRONT SEAT,L	87458AR06A	1	LINK ASSY - F		5/3/2006
ADJUSTER ASSY-FRONT SEAT,L					3/20/2006
ADJUSTER ASSY-FRONT SEAT,L					5/30/2006
ADJUSTER ASSY-FRONT SEAT,L					12/15/2005
ADJUSTER ASSY-FRONT SEAT,L					3/16/2006

ADJUSTER ASSY-FRONT SEAT,L					4/6/2006
ADJUSTER ASSY-FRONT SEAT,L	87458AR06A	1 LINK ASSY - F			5/15/2006
ADJUSTER ASSY-FRONT SEAT,RH					5/20/2005
ADJUSTER ASSY-FRONT SEAT,L					4/25/2006
ADJUSTER ASSY-FRONT SEAT,L					1/5/2006
ADJUSTER ASSY-FRONT SEAT,L	87458AR06A	1 LINK ASSY - F	VORHHA6498	1	2/17/2006
ADJUSTER ASSY-FRONT SEAT,L	SUBLTRENTX	1			2/17/2006
ADJUSTER ASSY-FRONT SEAT,L					6/22/2006
ADJUSTER ASSY-FRONT SEAT,L					3/2/2006
ADJUSTER ASSY-FRONT SEAT,L					6/5/2006
ADJUSTER ASSY-FRONT SEAT,L					3/17/2006
ADJUSTER ASSY-FRONT SEAT,L					5/12/2006
ADJUSTER ASSY-FRONT SEAT,L	VORHH46405	1	VORPH46405	1	2/28/2006
ADJUSTER ASSY-FRONT SEAT,L					12/22/2005
ADJUSTER ASSY-FRONT SEAT,L					1/11/2006
ADJUSTER ASSY-FRONT SEAT,L					2/13/2006
ADJUSTER ASSY-FRONT SEAT,L					4/6/2006
ADJUSTER ASSY-FRONT SEAT,L					5/10/2006
ADJUSTER ASSY-FRONT SEAT,L					3/22/2006

VIN: JN8AZ08TX5W[redacted]





VIN: JN8AZ08W75W[redacted]



KNOWN GOOD BRACKET FOR COMPARISON



VIN: JN8AZ08W75W[redacted]

Top View, impact witness marks



VIN: JN8AZ08T85W[redacted]

JN8AZ08T65W[redacted] / Drivers Seat Assembly













JN8AZ08W56W[redacted] Driver's Seat Assembly





JN8AZ08W56W[redacted] Driver's Seat Assembly



JN8AZ08W56W[redacted] Driver's Seat Assembly





JN8AZ08W56W[redacted] Driver's Seat Assembly



JN8AZ08W56W[redacted] Driver's Seat Assembly



Code-PNC	Desc-PNC	VIN	Model-Year	Code-NML-Prod	Code-NNA-Model	Num-Eng-Serial	Color-Ext	Color-Int
87653	SLIDE ASS'Y	JN8AZ08T85W[redacted]	2005	Z50	07215	VQ35-624784	KH3	G
87653	SLIDE ASS'Y	JN8AZ08TX5W[redacted]	2005	Z50	07215	VQ35-565354	AX5	G
87653	SLIDE ASS'Y	JN8AZ08W75W[redacted]	2005	Z50	07815	VQ35-421021	BW9	C
87653	SLIDE ASS'Y	JN8AZ08T75W[redacted]	2005	Z50	07215	VQ35-389611	QX1	C

Code-Plant	Date-Mfg	Date-In-Svc	Code-AssDist	Code-Acc	POE	Code-SellRegion	Code-SellDlr	St-SellDlr
W	8/1/2005	9/30/2005	US	C03,F01,L92,M	34	34	19068	FL
W	6/1/2005	7/21/2005	US	C03,L92,M94,N	44	44	3753	CA
W	12/14/2004	3/28/2005	US	C03,L92,Z99	44	24	3690	MN
W	11/16/2004	4/15/2005	US	C03,F01,L92,M	44	44	110B	CA

Num-Ctrl	Code-Class	Code-ClmStat	St-SvcDlr	Code-SvcDlr	Date-RO	Num-RO	Mileage	Code-CS
1901	0	2	FL	19068	7/28/2006	263263A	9,999	ZE
1901	0	2	CA	3753	6/7/2006	2832391	21,924	ZE
1901	0	2	OH	3473	8/2/2006	1097911	23,503	ZH
1903	0	2	CA	110B	8/10/2006	203679C	24,196	ZL

Code-CT	Code-Comp	Comm-Cust
01	BF	CUST STATES L,F SEAT BOTTOM BOTTOMS OUT SOP IN
32	BF	LF SEAT LOOSE:
32	BF	CUSTOMER STATES SEAT LEANING TOWARDS WINDOW:
32	BF	DRIVERS SEAT CREAKS

Comm-Tech	Claim$	LaborHrs	Labor$	Part$
FRAME CRACKED REQ REPL	$ 553.85	1.30	$ -	$ 503.85
FRAME BROKEN RREPLACE FRAME SEE SUBLET MAX DOLLAR ALLOWANCE UNDER WARRANTY 106 60:	$ 610.45	1.30	$ -	$ 503.85
FOUND SEAT FRAME LEANING TOWARDS WINDOW REPLACED FRAME:	$ 629.38	1.30	$ 125.53	$ 503.85
.	$ 620.20	1.30	$ 116.35	$ 503.85

Date-CSR	Code-Op1	Desc-Code-Op1	Code-Op2	Desc-Code-Op2	Code-Op3	Desc-Code-Op3	Num-Part1	Qty-Part1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA06A	1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA06A	1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA06A	1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA06A	1

Desc-Part1	Num-Part2	Qty-Part2	Desc-Part2	Num-Part3	Qty-Part3	Desc-Part3	Date-SysAdd
ADJUSTER AS							8/14/2006
ADJUSTER AS							8/14/2006
ADJUSTER AS							8/4/2006
ADJUSTER AS							8/14/2006

Add to page <18/28> new step & photograph as follows

orijinal step page <19/28>

44

41 Loosen the belt B R K T nuts then remove the BRKT



45

Modifier the new step and sentence with picture.

orijinal step page <19/28>

45

46 Place the new Front and Rear lifter link assembly onto the seat lift adjust assembly. Then, re-install the ADP CU bracket onto the seat adjust assembly.

LINK ASSY-RR LIFTER
(P/#: 87473-CA00A)

LINK ASSY-FR,FR SEAT
(P/#: 87458-CA08A)

Add the part# to photograph of front Link.

Then revise the step No & pages.

orijinal step page <19/28>

Remove the old Lifter Link Assembly
(2 nuts) from the seat lift adjuster assembly.

Remove the old Front & Rear Lifter Link
Assembly from the seat lift adjuster assembly.
(4 nuts each bracket)

Modifier the new step and
sentence.

orijinal step page <19/28>

Place the new lifter link assembly onto
the seat lift adjust assembly. Then, re-
install the ADP CU bracket onto the
seat adjust assembly.



NISSAN NORTH AMERICA, INC.
Copyright ©

SERVICE BULLETIN

Classification:	Reference:	Date:
BT05-012~~5~~	NTB05-043~~5~~	Draft, do not release

2003-200~~5~~7 MURANO; DRIVERS SEAT NOISE AND / OR ROCKS BACK AND FORTH

The Parts Information and Applied Date sections has been amended.
No other content has been changed.

APPLIED VEHICLE(S): 2003-200~~5~~7 Murano (Z50)
APPLIED DATE: Vehicles built before ~~August 2005~~ Jan. 18, 2007

IF YOU CONFIRM

The driver's seat is noisy and / or rocks back and forth slightly.

ACTION

Disassemble the seat as shown, install the parts listed below and reassemble the drivers seat.

PARTS INFORMATION

Insert here

DESCRIPTION	PART #	QUANTITY
Lifter Link Assembly FR-LH (2003-2005 MY for vehicles built before 8/05)	87458-AR06A	1
Lift Motor-FR-LH (w/Memory System) (2003 MY for vehicles built before 7/03)	87454-CA61A	1
Lift Motor-FR-LH (w/o Memory System) (2003 MY for vehicles built before 7/03)	87454-CA01A	1
Lifter Link Assembly RR-LH	87473-CA00A	1

CLAIMS INFORMATION

Submit a Primary Failed Part (PP) line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPR Left Front Power Seat	(1)	VX43AA	ZL	46	1.6 hrs

(1) Reference the FAST Parts Catalog and use the applicable LH Front Seat Adjuster Assy P/N as the PFP.

IMPORTANT: The purpose of "ACTIONS" (above) is to give you a quick idea of the work you will be performing. You MUST closely follow the entire Service Procedure (starting on page 2) as it contains information that is essential to successfully completing the repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

Exploded View of Front Seat (For Reference)



1	Seatback board	2	Headrest	3	Headrest holder (locked)
4	Headrest holder (free)	5	Lumbar support lever knob	6	Seatback trim
7	Seatback pad	8	Seatback frame	9	Inner stay
10	Side air bag module	11	Seat cushion trim	12	Seat cushion pad
13	Seat cushion frame	14	Power seat harness	15	Seat cushion inner finisher
16	Reclining inner device	17	Reclining device rod	18	Reclining outer device
19	Seat belt buckle	20	Seat lifter link slide assembly	21	Power seat switch
22	Pedal adjusting switch	23	Seat cushion outer finisher	24	Slide & lifter switch knob
25	Reclining switch knob	26	Seat cushion under cover	27	Seat cushion front finisher
28	Seat control unit	29	Seat cushion outer cover		

SERVICE PROCEDURE

1. Remove headrest.

2. Move the seat bottom forward to remove both rear seat rail covers and seat anchor bolts.

3. Move the seat bottom rearward to remove both front seat rail covers and seat anchor bolts.

4. Use the "tilt up" switch to move the seat bottom to the highest position.

5a Record all radio presets.

5b Turn the ignition key OFF.

6. Disconnect both battery cables (negative cable first) and wait 3 minutes before going to the next step.

7. Lean the entire seat assembly backwards (so the seat back touches the rear seat) so you can reach the under side of the seat.

   Disconnect 1 side air bag connector and 2 ADP Control Unit connectors.



Figure 1

8. Cover the door sill plate and lower B-Pillar finisher with a clean dry cloth fender cover.

9. Carefully remove the seat assembly from vehicle and place it on a clean dry work surface.

10. Place the seat upside down, to reach the underside.

11. Remove 3 connectors from the LH side bracket, and then disconnect the connectors.



Figure 2



Figure 3

Figure 4

12. Remove power seat slide and tilt switche knobs from lower LH side finisher.



Figure 5

13. Use flat blade to release clip between the lower front and LH side finishers.



Figure 6

14. Lift up the lower side finisher.

Figure 7

15. Disconnect power seat switch connectors.

    Remove the power seat switch connector from the seat frame held by a clip.



Figure 8

16. Remove the LH seat slide finisher. (2 screws)



Figure 9

17. Release power seat switch harness from bracket.



Figure 10



Figure 11

18. Now remove LH lower side finisher.

Figure 12

19. Remove lower front finisher (2 clips).



Figure 13

20. Release elastic band from cushion spring.



Figure 14

21. Remove RH Seat Cushion Inner Finisher.


Figure 15

22. Remove seat back panel 2 clips located at lower end of seat back.



Figure 16

23. Disconnect the seat back panel and then slide it <u>up</u> and <u>off</u>.



Figure 17

24. Disconnect connectors at ADP control unit (CU) .



Figure 18

25. Remove seat harness from ADP CU bracket (1 clip).



Figure 19

26. Remove connector from ADP CU bracket.



Figure 20

27. Remove side air bag connector from ADP CU bracket (1 clip).

Figure 21

28. Remove connectors from ADP CU bracket (2 clips).

Figure 22



Figure 23

29. Disconnect seat slide motor connector.



Figure 24

30. Disconnect the tilt seat motor connectors.



Figure 25

31. Remove seat belt connector from seat frame and disconnect the connector.



Figure 26



Figure 27

32. Remove seat belt harness from seat lifter adjuster (1 clip).



Figure 28



Figure 29

33. Disconnect side air bag harness from seat cushion frame (2 clips).



34. Remove both clips at the back of the seat cushion frame. (see Figures 33 and 34)



Figure 33



Figure 34

35. Remove the bolts at each pivot end (14mm bolt). This will detach the seat cushion pad from seat back pad.



Figure 35

36. Remove seat cushion trim (3 clips on each side, 1 clip along front, and 1 clip along rear).

37. Disconnect seat heater switch connector, located between seat back and seat bottom.



Figure 36

38. Push harness through seat springs and out of the way.


Figure 37

39. Remove the Seat Cushion Frame (4 nuts – 12mm)



Figure 38



Figure 39

40. Remove side brackets from seat lift adjuster (Both sides)

- Long bracket (LH side)



Figure 40

- Short bracket (RH side)



Figure 41

41. Remove Seat Lifter Motor Assembly (4 bolts & 2 nuts) from Seat Lift Adjuster Assembly.



Figure 42

IMPORTANT: Please pay close attention to the next step.

42. **Install Seat Lift Adjuster Assembly back into the vehicle and tighten down all 4 seat anchor bolts.**

NOTE: This step is IMPORTANT to maintain proper alignment. It will securely hold the seat lift adjust assembly during removal of the lifter link assembly.

43. Remove ADP control unit (CU) bracket (2 nuts).



Figure 43

44. Remove the old Lifter Link Assembly (2 nuts) from the seat lift adjuster assembly.



Figure 44

45. Place the new lifter link assembly onto the seat lift adjust assembly. Then, re-install the ADP CU bracket onto the seat adjust assembly.

    Tighten the nuts for the lifter link assembly and ADP CU bracket to the specified torque:

    Torque to 11.0-14.5 N•M (1.12-1.47 kg-m, 8.1-10.7 ft-lb.)



Figure 45

46. Remove the seat lift adjuster assembly from the vehicle.

47. **For 2003 MY Vehicles:**
Install the **NEW** seat lifter motor assembly onto the seat lift adjuster assembly.

Install the nuts and bolts finger tight, in the following order:
1. **N1** and **N2**.
2. **B5** and **B6**.
3. **B3** and **B4**.

Torque to 11.0-14.5 N•M (1.12-1.47 kg-m, 8.1-10.7 ft-lb.) in the following order:
1. **B5** and **B6**.
2. **B3** and **B4**.
3. **N1** and **N2.**



Figure 46

48. **For 2004 &2005 MY Vehicles:**
Re-install the original seat lifter motor assembly onto the seat lift adjuster assembly. Tighten the nuts and bolts using the same sequence as Step 47 above.


Figure 47


Figure 48

49. Install side support bracket (both sides)

- Install the mounting bolts for the Long bracket (LH side). Torque to 11.0-14.5 N•M (1.12-1.47 kg-m, 8.1-10.7 ft-lb.)



Figure 49

- Install the mounting bolts for the Short bracket (RH side). Torque to 11.0-14.5 N•M (1.12-1.47 kg-m, 8.1-10.7 ft-lb.)



Figure 50

50. Re-install seat cushion frame to the seat lift adjuster assembly.



Figure 51

51. Install the front side of cushion frame into the slots.

a. Lock in front with nuts, 1 turn each. (see Figure 52)

b. Next install the rear side of cushion frame into slots by pulling in a rearwards direction.

c. Lock in rear with nuts.

d. Now tighten down all 4 nuts completely.

NOTE:
Improper tightening (nuts not tight enough) may cause a customer to come back with complaint of a spring-type noise.



Figure 52

52a. Route the seat harness (which is attached to the seat back) through the cushion spring as shown and

Figure53

52b. Attach to seat cushion frame (2 clips).



Figure 54

53. Turn the seat bottom frame upside down. (see Figure 55)

a. Connect ADP CU connectors.

b. Connect tilt motor connectors.

c. Connect front slide motor connector.

d. Connect seat belt connector and attach it to frame (1 clip).

e. Re-attach seat belt harness to frame (1 clip).



Figure 55

54. Route air bag harness under seat lifter motor assembly and attach to frame (2 clips).



Figure 56

55. Re-attach connectors to ADP CU bracket (2 clips).



Figure 57

56. Turn seat bottom frame over so it's right side up. Place seat cushion pad onto seat cushion frame, attach the trim on both sides (3 clips on each side).

57. Connect seat heater connector.



Figure 58

58. Attach seat back to the seat bottom. Install 2 bolts at seat hinge (both sides). Then tighten the nuts and bolts to the specified torque,

Torque specs for the pivot bolts are: 43.1-54.0 Nm, 4.4-5.5 kg-m, 32-40 in –lb.


Figure 59

59. Turn the seat assembly upside down to access the bottom.

a. Attach clips to the front. (see Figure 60)



Figure 60

b. Attach rear clips of the seat cushion trim to the frame.



Figure 61

60. Attach elastic band to cushion spring. Make sure it is pulled tight



Figure 62

61. Attach seat back panel at the top, then reattach two clips at the bottom.

Figure 63

62. Install LH seat <u>slide trim.</u>



Figure 64

63. Install LH seat <u>side finisher</u>.

a. First, connect power seat switch connectors together

b. Then re-attach connector to seat frame (1 clip).



Figure 65

64. Secure the LH seat side finisher in place at the hinge end, then push the connector through seat frame bracket.



Figure 66

65. Attach 3 connectors to seat frame bracket (3 clips), then connect the connectors.



Figure 67

66. Install power seat switch knobs.



Figure 68

67. Install front lower finisher.

a. Hook LH side first,

b. then snap RH side in place.

Figure 69

68. Install RH Seat Cushion Inner Finisher.



Figure 70

69. Install seat assembly into the vehicle.

a. Lean the entire seat assy back (so the seat back touches the rear seat) to access the under side of the seat.

b. Connect the 3 connectors at front of seat



Figure 71

70. Tighten seat anchor bolts and install front and rear seat rail covers (both sides)

71. Reconnect battery, positive cable first.

72. Reprogram radio presets and set the clock.

Code-PNC	Desc-PNC	VIN	Model-Year	Code-NML-Prod	Code-NNA-Model	Num-Eng-Serial	Color-Ext	Color-Int
87653	SLIDE ASS'Y	JN8AZ08T26W	2006	Z50	07416	VQ35-837196	EY0	C
87653	SLIDE ASS'Y	JN8AZ08T26W	2006	Z50	07416	VQ35-837196	EY0	C
87653	SLIDE ASS'Y	JN8AZ08TX6W	2006	Z50	07416	VQ35-790874	K23	G
87653	SLIDE ASS'Y	JN8AZ08W06V	2006	Z50	07716	VQ35-764056	AX5	C
87653	SLIDE ASS'Y	JN8AZ08W16V	2006	Z50	07816	VQ35-652011	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W26V	2006	Z50	07816	VQ35-806198	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W26V	2006	Z50	07816	VQ35-806198	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W46V	2006	Z50	07816	VQ35-680200	K21	G
87653	SLIDE ASS'Y	JN8AZ08W46V	2006	Z50	07616	VQ35-695494	AX5	G
87653	SLIDE ASS'Y	JN8AZ08W86V	2006	Z50	07816	VQ35-679690	QX1	C
87653	SLIDE ASS'Y	JN8AZ08W96V	2006	Z50	07816	VQ35-667279	K21	G
87653	SLIDE ASS'Y	JN8AZ08W96V	2006	Z50	07816	VQ35-687973	K23	G
87653	SLIDE ASS'Y	JN8AZ08W96V	2006	Z50	07816	VQ35-851839	K23	G

Code-Plant	Date-Mfg	Date-In-Svc	Code-AssDist	Code-Acc	POE	Code-SellRegion	Code-SellDlr	St-SellDlr
W	3/18/2006	5/11/2006	US	C03,G04,K69,L	44	32	1971	TN
W	3/18/2006	5/11/2006	US	C03,G04,K69,L	44	32	1971	TN
W	1/31/2006	4/7/2006	US	C03,G04,K69,L	44	32	872A	TX
W	1/23/2006		US	C03,G02,K69,L	36			
W	9/21/2005	11/22/2005	CA					
W	2/15/2006	4/13/2006	US	C03,G04,K69,L	36	36	11025	MD
W	2/15/2006	4/13/2006	US	C03,G04,K69,L	36	36	11025	MD
W	10/11/2005	1/2/2006	US	C03,K69,L92,N	26	26	2157	NY
W	10/26/2005	1/16/2006	US	C03,K69,L92	36	36	3960	NC
W	10/11/2005	11/23/2005	CA					
W	9/23/2005	3/4/2006	CA					
W	10/18/2005	1/27/2006	CA					
W	3/31/2006		US	C03,G05,K69,L	44			

Num-Ctrl	Code-Class	Code-ClmStat	St-SvcDlr	Code-SvcDlr	Date-RO	Num-RO	Mileage	Code-CS
1901	0	2	TN	2409	8/1/2006	2425152	2,215	ZE
1902	3	2	TN	2409	8/1/2006	2425153	2,215	ZE
1902	0	2	TX	2190	8/10/2006	203478A	7,458	ZE
1901	0	2	PA	2840	7/10/2006	653181	2,995	ZL
1906	0	2	SK	21049	5/5/2006	317435A	11,981	ZE
1902	0	2	MD	11025	5/15/2006	308491B	1,471	ZE
2201	2	2	MD	11025	5/15/2006	308491B	1,471	ZE
1901	0	2	NY	2157	7/24/2006	3446131	7,692	ZE
1901	0	2	NC	3571	8/2/2006	28201A	23,121	ZX
1905	0	2	QC	52235	5/24/2006	93435C	14,631	ZL
1901	0	2	ON	44145	5/18/2006	149809B	9,754	ZJ
1901	0	2	QC	52112	4/3/2006	247152A	57,769	ZE
1901	0	2	IA	614	7/19/2006	2693571	15	ZE

Code-CT	Code-Comp		Comm-Cust	Comm-Tech	Claim$	LaborHrs	Labor$	Part$
32	BF		CUSTOMER S	INTERNAL FAI	$ 606.83	1.30	$ 101.40	$ 505.43
32	BF		LEFT FRONT S	INTERNAL FAI	$ 606.83	1.30	$ 101.40	$ 505.43
32	BF		C,S DRIVERS	7458 FOUND L	$ 683.69	1.30	$ 119.60	$ 564.09
26	BF		L F SEAT CLIC	SET ADJUSTE	$ 615.93	1.30	$ 110.50	$ 505.43
32	BF				$ 220.65	1.30	$ 83.79	$ 136.86
42	BF		CUSTOMER S	VERIFY CONC	$ 637.34	1.30	$ 95.81	$ 541.53
42	BF		CUSTOMER S	VERIFY CONC	$ 60.19	.00	$ -	$ 60.19
32	BF	1	CUSTOMER S	L F SEAT FRA	$ 626.05	1.30	$ 122.20	$ 503.85
01	BF	1	FRONT SEATS	FOUND LEFT	$ 592.25	1.30	$ 88.40	$ 503.85
46	BF				$ 89.57	1.30	$ 89.57	$ -
46	BF				$ 246.00	1.30	$ 109.14	$ 136.86
42	BF				$ 227.80	1.30	$ 90.94	$ 136.86
32	BF		CUSTOMER W		$ 609.43	1.30	$ 104.00	$ 505.43

Date-CSR	Code-Op1	Desc-Code-Op1	Code-Op2	Desc-Code-Op2	Code-Op3	Desc-Code-Op3	Num-Part1	Qty-Part1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA66A	1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA66A	1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA66A	1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA66A	1
5/31/2006	VH40AA	RPL LEFT SE/					87450CA01A	1
5/31/2006	VH40AA	RPL LEFT SE/					87450CA66A	1
5/31/2006							87450CA66A	0
7/31/2006	VH40AA	RPL LEFT SE/					87450CA010	1
8/31/2006	VH40AA	RPL LEFT SE/					87450CA06A	1
5/31/2006	VH40AA	RPL LEFT SE/					87450CA01A	0
6/30/2006	VH40AA	RPL LEFT SE/					87450CA06A	1
4/30/2006	VH40AA	RPL LEFT SE/					87450CA06A	1
7/31/2006	VH40AA	RPL LEFT SE/					87450CA66A	1

Desc-Part1	Num-Part2	Qty-Part2	Desc-Part2	Num-Part3	Qty-Part3	Desc-Part3	Date-SysAdd
ADJUSTER AS							8/21/2006
ADJUSTER AS							8/21/2006
ADJUSTER AS							8/11/2006
ADJUSTER AS							7/25/2006
ADJUSTER AS							5/10/2006
ADJUSTER AS	VORHKH1497		1				5/18/2006
ADJUSTER AS	SUBLTRENTX		1				5/18/2006
ADJUSTER AS							7/25/2006
ADJUSTER AS							8/7/2006
ADJUSTER AS							5/25/2006
ADJUSTER AS							5/26/2006
ADJUSTER AS							4/11/2006
ADJUSTER AS							7/24/2006