TEREX®

Cynthia Glass
General Engineer, RMD
US DOT/NHTSA
1200 New Jersey Ave, SE
Washington, DC 20590
202-366-2920

January 13, 2015

Re: EQ 14-012

Dear Ms. Glass,

This letter is in response to the information request for EQ 14-012. Terex Advance Mixer, Inc. has conducted a thorough analysis of the 42 throttle pedal spring assemblies we purchased from Williams Controls, Inc. Terex has not received any field reports or warranty claims where the failure mode is consistent with the type of defect that is being investigated.

We have reviewed Williams Controls, Inc.'s assessment of the issue and Terex concurs with their findings.

Therefore, Terex Advance Mixer, Inc. is not conducting a recall on this issue at this time.

Best regards,

Patrick J. Merfeld

Director - Product Safety
Terex Corporation
106 12th Street SE
Waverly, IA 50677
319-483-4536