FERRARA
FERRARA FIRE APPARATUS, INCORPORATED

By Electronic Mail (Kelly.Schuler@DOT.GOV)

May 27, 2016

Kelly Schuler
Safety Recall Specialist
Recall Management Division
Office of Defects Investigation Enforcement
(202) 366-5227

RE: – Safety Recall 15E-065
EQ16-002 Investigation

Based on our evaluation we have found no issue with the Marmon Herrington Drive Axle Flange Yoke torque values. This axle is rarely purchased and the (3) three suspect axles were installed on a single customers (3) three trucks. These trucks happen to be in our service center and we verified that the flange torque values were to specification. Ferrara Fire feels that this condition for these (3) three axles does not present an unreasonable risk to motor vehicle safety in the United States.

If you require additional information, please do not hesitate to contact me.

Sincerely,

Ronald G. Lavicott

Ronald G. Lavicott
Director of Chassis Engineering
Ferrara Fire Apparatus, Inc.
27855 James Chapel Road
Holden, LA 70744