INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

[redacted]

Adv: 270 GLEN SPINA	Tag 2448	License BJ13S	JF2SJARC5 J[redacted]	Page 1	Invoice [redacted]

Invoice to

[redacted]
SPRING, TX [redacted]
Cell: [redacted] Work: [redacted] Work Ext: [redacted]

Driver/Owner Information

[redacted]
SPRING, TX [redacted]
Cell: [redacted] Work [redacted] Work [redacted]

For Office Use

Odometer in: 4230 Out: 4230 | Dist: JF1 WAR R W Final | MFG [redacted]

Begin: 09/19/18 | Done: 10/04/18 | Invoiced: 10/04/18 11:24 GS

Vehicle Information

18 SUBARU FORESTER 2.5I LTD 4DR SUV WHITE

Stock#: [redacted]

Inservice: 09/21/17 | Sold: 09/21/17

Customer Concern

Concern 51: CUSTOMER STATES SRS LIGHT STAYS ON

Cause: INTERNAL FAILURE

Correction: TECH FOUND SRS LIGHT ON - TECH PREFORMED DIAG AND FOUND PASSENGER SIDE SEAT BOTTOM NEEDING TO BE REPLACED TECH REPLACED PASSENGER SIDE SEAT BOTTOM RESET LIGHT AND TEST DROVE ALL OK AT THIS TIME

51-1: TECH FOUND SRS LIGHT ON - TECH PREFORMED DIAG AND FOUND PASSENGER SIDE SEAT BOTTOM NEEDING TO BE REPLACED TECH REPLACED PASSENGER SIDE SEAT BOTTOM RESET LIGHT AND TEST DROVE ALL OK AT THIS TIME

Comment: PICK AUTH NUMBER 74R107 -

Parts

Part Number	PO#	Note	Description
SUB 64139SG160LL			CUSHION AY OCCUPANT

Parts: Count 1.00 Allowance: 199.37

Tech 068 CERVANTES, EDWI

COND CODE : URD
FAIL CODE : 43

51-1

COND CODE : URD
FAIL CODE : 43

Type: W

Operation	Tech	Units	Amount
B820496	068	0.8	92.93
C303708	068	0.1	11.62

Qty	List	Sell	
1	866.84	866.84	866.84

Subtotal

PARTS	866.84
LABOR-MECHANICAL	104.55
TOTAL CHARGE FOR CONCERN	971.39

UCS©2004

Scanned with CamScanner