INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

Adv: 248 DONALD BUCKLES	Tag **1761**	License [redacted]	JF2SJAGC9[redacted]	Page 1 (Last)	Invoice [redacted]

Invoice to	**Driver/Owner Information**
[redacted] SCHERTZ, TX [redacted] Cell: [redacted] Work: [redacted]	[redacted] SCHERTZ, TX [redacted] Cell: [redacted] Work: [redacted]

For Office Use			**Vehicle Information**		
Odometer in: 9995 Out: 9995		Dist: JF1 WAR W Final	17 SUBARU FORESTER 2.5I PREM 4DR SUV WHITE		
	MFG: 066001		Stock#: 00S70103	Inv Acct: 2240	
Begin: 06/27/17	Done: 06/27/17	Invoiced: 06/27/17 13:04 DB	Inservice: 08/16/16	Production: 08/16/16	Sold: 08/16/16

Customer Concern

Concern 51	C/S THAT THE PASSENGER SIDE AIR BAG LIGHT DOESN'T OUT WHEN OCCUPIED					
Cause	SCANNED FOR CODES FOUND B1650.					
Correction	INSPECTED SYSTEM FOUND AN OPEN CIRCUIT IN THE ODS					
51 - 1	REPLACED PASSENGER SIDE SEAT BOTTOM WITH NEW SENSOR VERIFIED NORMAL OPERATION AT THIS TIME					
Parts	Part Number	PO#	Note	Description		
	SUB 64139SG060LL		NSTK	CUSHION AY OCCUPANT		
	Parts: Count 1.00	Allowance:	205.69			
	Tech 163 BEMIS JR, THOMA					
				COND CODE : URC		
				FAIL CODE : 39		
51 - 1				COND CODE : URC		
				FAIL CODE : 39		
Type: W						

Operation	Tech	Units	Amount
B820496	163	0.8	77.60
C820201	163	0.9	87.30

Qty	List	Sell	
1	685.64	685.64	685.64

Subtotal

PARTS	685.64
LAB-MECHANICAL	164.90
TOTAL CHARGE FOR CONCERN	850.54

Summary of Charges for Invoice W11455	
PARTS	685.64
LAB-MECHANICAL	164.90
TOTAL CHARGE	850.54

Payment Distribution for Invoice W11455	
TOTAL CHARGE	850.54
FAC WARRANTY	**850.54**

If you have any questions - please see DONALD BUCKLES

[redacted]

Scanned by CamScanner