Tester Software Version

Issue #	Part Info:	Group(s) Affected:		
15	Tester Software	Service ☐ Parts ☐ Roadside Assistance ☐ Sales ☐ Vehicle delivery/Logistics ☐		

Condition:
Tools were up to date on software versions.

Observed Situation:
Extra effort had been in place to update the software versions of the battery tester GR8 and V8150, and this is commendable!

Concern:
None on the dealer side.

A possibility exists on distributor side to miss updates to Tester software. If necessary, offer to update their tester software.



Suggested Change:
No change on the dealer side, but ensure the Interstate driver's battery tester is up to date.

FYI: New versions of software in the future will focus on CCA as the primary test instead of model or JIS. Continue to use the "model" method to generate codes as currently that is the best way to get the warranty code. When doing a second test, use CCA and in the second test.

The CCA by "Model" should be very similar on the original test and subsequent tests by CCA on the printout.

Dealer Concerns:

