
Replacement Batteries Not Adequately Charged

Issue #	Part Info	Group(s) Affected:		
7	Battery	Service ☐ Parts ☐ Roadside Assistance ☐ Sales ☐ Vehicle delivery/Logistics ☐		

Condition
New replacement batteries may not be adequately charged coming off the Interstate Truck



Observed Situation:
Low battery voltage was observed on brand new batteries just delivered.

Concern:
Low voltage during storage may impact long term durability.

Suggested Change
Monitor incoming new replacement batteries for voltage, if low, address concern with Interstate supplier and notify TMS of the situation via DPR.

Dealer Concerns: